ARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH SE TION

01-5-2190 № 13413

OPERATIONS PERMIT

	, ,
Name: (owner) CUARTN Builder	New Installation Septic Tank
Property Location: SR# 1542 OID Buras Crash	Repairs Nitrification Line
Property Location: SR# 1542 OID Builde Crack Subdivision Sandy Grove	Lot #
	Quadrant #
Contractor: <u>Ed Curin</u>	Registration #
Basement with Plumbing: Garage:	
Water Supply:	
Distance From Well:ft.	
Following are the specifications for the sewage disposal system on above captioned property.	
Type of system:	
Size of tank: Septic Tank: 1000 gallons Pr	ump Tank: gallons
Subsurface No. of exact length of each ditch 100 f	width of depth of ft. ditches 18-22 in.
French Drain: Linear feet	
Date:	10-25-01
PERMIT NO. 1846Z inspected	d by: Sames & Markart Free Environmental Health Specialist
Home Will ALN Pout Cor Repair VIOLA LN	70'_7