



New Bathroom

Closet

Vanity

Shower

Sep. Tank

Back water tank

Property line

2V12

14' 15"

6' 11"

3' 6"

11' 5"

House

11' 5"

1/2" 5" x 5"



Job #33601

Septic Blue Inspection Form NC

SEPTIC INSPECTION FORM

Date

2020-05-21

Service Address

1626 Chalybeate, Angier, NC, 27501

SECTION 2

Does this evaluation / inspection meet the requirements of state and local agencies?

YES

SECTION 4

Septic tank distance from foundation in feet.

20

SECTION 6

What is the separation between the septic system and the well or state /county body of water

10

SECTION 8

Any evidence of malfunction?
(Please check all applicable observed conditions)

NO EVIDENCE OF MALFUNCTION

IF TANK IS BEING OPENED AND PUMPED , PLEASE ANSWER THE FOLLOWING QUESTIONS:

Yes

SECTION 11

Liquid level in tank

Normal

Customer Name

Mildred Crissmon

SECTION 1

Are there any state or local requirements regarding the evaluation of a septic system?

NO

SECTION 3

Location of system:

BACK

SECTION 5

Estimated size of tank:

1000

SECTION 7

DOES THE SEPARATION OF THE SEPTIC SYSTEM AND WELL/BODY OF WATER MEET LOCAL REQUIREMENTS?

N/A

SECTION 9

Is system working properly?

yes

SECTION 10

Septic tank material:

Concrete

SECTION 12

Does the Septic tank have a baffled wall?

Yes