



**Harnett County**  
108 EAST FRONT STREET  
LILLINGTON, NC 27546  
Phone:  
Fax:

12/29/2020

**SUBJECT: BRES2009-0019**  
**BUILDING RESIDENTIAL**

To: Danny Ray Fisher

Here are the results of all Inspections located at **604 WARREN RD:**

Inspection Type: ENVIR OPERATIONS PERMIT  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: EH Bucket  
Result:  
Remarks:  
Notes:

Inspection Type: FOOTING  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Deen Taylor  
Result:  
Remarks:  
Notes:

Inspection Type: FOUNDATION  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Deen Taylor  
Result:  
Remarks:  
Notes:

Inspection Type: MONO SLAB  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Deen Taylor  
Result:  
Remarks:  
Notes:



**Harnett County**  
108 EAST FRONT STREET  
LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: OPEN FLOOR  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Deen Taylor  
Result:  
Remarks:  
Notes:

Inspection Type: SLAB  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Deen Taylor  
Result:  
Remarks:  
Notes:

Inspection Type: TAX INSPECTION  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Tax Inspection  
Result:  
Remarks:  
Notes:

Inspection Type: UNDER SLAB TRADES  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Deen Taylor  
Result:  
Remarks:  
Notes:

Inspection Type: FINAL\*\*  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: Deen Taylor  
Result:  
Remarks:  
Notes:





**Harnett County**  
108 EAST FRONT STREET  
LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: ROUGH IN  
Scheduled Date/Time: 10/1/2020  
Completed Date/Time: 10/1/2020  
Inspector: Deen Taylor  
Result: DISAPPROVED

Remarks:

Notes: Rodent proof tubs and showers. Install nail guards the top and bottom plates. Fire caulk all holes in top and bottom plate. Install mid story guides for plumbing vents  
Rodent proof tubs and showers. Install nail guards the top and bottom plates. Fire caulk all holes in top and bottom plate. Install mid story guides for plumbing vents

Inspection Type: INSULATION  
Scheduled Date/Time: 10/2/2020  
Completed Date/Time: 10/2/2020  
Inspector: Deen Taylor  
Result: APPROVED

Remarks:

Notes:

Inspection Type: ROUGH IN  
Scheduled Date/Time: 10/2/2020  
Completed Date/Time: 10/2/2020  
Inspector: Deen Taylor  
Result: APPROVED

Remarks:

Notes:

Inspection Type: FINAL\*\*  
Scheduled Date/Time: 12/23/2020  
Completed Date/Time: 12/23/2020  
Inspector: Deen Taylor  
Result: DISAPPROVED

Remarks:

Notes: Repair sheet rock panel. All receptacle covers must be installed. Where double vanity was installed at master bathroom there must be a receptacle for each sink