

Harnett County

108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

10/28/2020

SUBJECT: **BRES2010-0020**

BUILDING RESIDENTIAL

To: HORTON DENNY LEE JR

Here are the results of all Inspections located at 64 TEAK WOOD CT:

Inspection Type: ELECTRICAL UNDERGROUND

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result:

Remarks: Approved on old permit

Notes:

Inspection Type: BONDING

Scheduled Date/Time: Completed Date/Time:

Inspector: Slade Burton Lawson III

Result: Remarks:

Notes: Fenced in yard, but no dogs will be out and you have permission to enter back yard. electrical

is behind the rv on property.

Inspection Type: ZONING Scheduled Date/Time: 10/13/2020

Completed Date/Time: 10/13/2020 09:30 AM

Inspector: Kyle Holder Result: APPROVED

Remarks:

Notes: Fenced in yard, but no dogs will be out and you have permission to enter back yard.

Inspection Type: FINAL
Scheduled Date/Time: 10/13/2020
Completed Date/Time: 10/14/2020

Inspector: Slade Burton Lawson III

Result: DISAPPROVED

Remarks:

Notes: This is electrical final

Barrier and gate requirements not met. Sent email to homeowner with code references where

lacking





Harnett County

108 EAST FRONT STREET

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FINAL**
Scheduled Date/Time: 10/13/2020
Completed Date/Time: 10/14/2020

Inspector: Slade Burton Lawson III
Result: APPROVED W/EXC

Remarks:

Notes: Pool Final

This is for electrical. Ref. Pervious permit #08500020889

Inspection Type: FINAL**
Scheduled Date/Time: 10/22/2020
Completed Date/Time: 10/22/2020

Inspector: Slade Burton Lawson III

Result: APPROVED

Remarks: Notes: