

HTE # 05-5-11199R

# OPERATIONS PERMIT

Name: (owner) Lemuel D. Black III  New Installation  Septic Tank  Repair

Property Location: SR# 1126  Nitrification Line  Expansion  
Subdivision \_\_\_\_\_ Lot # \_\_\_\_\_ Tax ID # \_\_\_\_\_ Quadrant # \_\_\_\_\_

Contractor: Ottis Strickland Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:

Water Supply:  Well  Public  Community  
Distance From Well: 100 ft.

**Following are the specifications for the sewage disposal system on above captioned property.**

Type of system:  Conventional  Other \_\_\_\_\_

Size of tank: Septic Tank: 1000 gallons Pump Tank: \_\_\_\_\_ gallons

Subsurface Drainage Field No. of ditches 4 exact length of each ditch 60 ft. width of ditches 3 ft. depth of ditches 24 in.

French Drain Required: \_\_\_\_\_ Linear feet Date: 3/21/2005

PERMIT NO. 21682 Inspected by: Benjamin McFarland, Jr.

