



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

3/2/2021

SUBJECT: BRES2012-0086
BUILDING RESIDENTIAL

To: Spotlight Pools

Here are the results of all Inspections located at **375 BAKERTOWN RD:**

Inspection Type: ELECTRICAL UNDERGROUND
Scheduled Date/Time:
Completed Date/Time:
Inspector: Ray Holder
Result:
Remarks:
Notes:

Inspection Type: FINAL**
Scheduled Date/Time:
Completed Date/Time:
Inspector: Ray Holder
Result:
Remarks:
Notes:

Inspection Type: ZONING
Scheduled Date/Time:
Completed Date/Time:
Inspector: Planning Bucket
Result:
Remarks:
Notes:

Inspection Type: BONDING
Scheduled Date/Time:
Completed Date/Time:
Inspector: Ray Holder
Result:
Remarks:
Notes:



Harnett County
108 EAST FRONT STREET
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: BONDING
Scheduled Date/Time: 3/2/2021
Completed Date/Time: 3/2/2021
Inspector: Ray Holder
Result: DISAPPROVED
Remarks:
Notes: Only 3 points of bonding to rebar need 4.