HTE #: BRES2102-0045R

HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

Name: Mark Santos Phone #: 814.464.4766

Address: 44 Wood Spring Ct. Fuquay-Varina, NC 27526

Name of Mobile Home Park or S/D: Olde Mill Village - Lot 29

Name of Owner (if different): Same

Address of Owner (if different): Same

Property Location (State Road name and #): 44 Wood Spring Ct. Fuguay-Varina, NC 27526

Purpose of Inspection: Deck Extension and Covered Porch [See Plans Attached]

The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs.

THIS INSPECTION IS VOID IF:

- 1. the intended use of the septic system should change, and/or
- 2. the system should fail or malfunction, and/or
- 3. the owner or tenant of the property change, and/or
- 4. after six months

BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM DO NOT DRIVE OR PARK ON SEPTIC SYSTEM

AUTHORIZATION OF EXISTING SYSTEM

Signature of Environmental Health Specialist

Date

44 WOOD SPRING CT

- ~ Extend exiting 10' x 12' deck by 10 feet
- ~ Cover 12' x 20' porch with 4:12 pitch roof
- ~ Attach additional 10' x 15' deck
- ~ Cover 10' x 10' of addition with 4.8:12 pitch roof
- ~ Remaing 10' x 5' uncovered
- ~ Stairs to extend off of 5' bumpout

