

Joe E Godwin Sr. , P.E., P.L.S.

Fleet Temple , P.E.

Jason E Godwin , P.L.S.



1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765

Email: [general@enochengineers.com](mailto:general@enochengineers.com)

[www.enochengineers.com](http://www.enochengineers.com)

## MATERIALS & TEST DIVISION

### FIELD REPORT

#### PROJECT

CLIENT:	BAREFOOT BUILDING CO	DATE:	10.5.21
PROJECT:	DET GARAGE FOOTING	CONTRACTOR:	ROBERT BAREFOOT
ADDRESS:	530 POPE LAKE RD	TECHNICIAN:	BH
LOT #:	ANGIER, NC		

#### TEST SUMMARY

PERFORMED SOIL BEARING CAPACITY EVALUATION AT SITE NOTED ABOVE. SOILS CONFIRMED A MINIMUM ALLOWABLE BEARING CAPACITY OF 2000 PSF AT ALL FOOTING LOCATIONS FOR DETACHED GARAGE.

#### TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %

DS

#### RETURN VISTIT REQUIRED?

YES

NO

DocuSigned by:

339EA4405059480...

11/22/2021

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 60 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying