HTE #: BRES2103-0088

HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

Name: Michael Socha	Phone #: 910-964-5598	
Address: 116 Mossburg Ct, (SR2604)		
Name of Mobile Home Park or S/D:		
Name of Owner (if different):		
Address of Owner (if different):		
Property Location (State Road name and #): 116 Mossburg Ct, (SR2604)		
Purpose of Inspection: 16' x 32' inground pool addition off back left corner of house		
The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs.		
 the intended use of the septic system should change, and/or the system should fail or malfunction, and/or the owner or tenant of the property change, and/or after six months 		
BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM DO NOT DRIVE OR PARK ON SEPTIC SYSTEM		
AUTHOR	IZATION OF EXISTING SYSTEM	
Made Al	REHS	4-8-21
Signature of Environmental Health	Specialist	Date