Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Description

System Type(s)

Site LTAR

Available Space (.1945)

Sheet: Property ID: Lot #:

File #: Code:

BABS 2104-0009

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant: Delic Frank Address: Date Evaluated: 4-21-21 Proposed Facility: Shop Silk Design Flow (.1949):													
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS .1942 Soil .1943 .1956 .1944				Profile				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Class & LTAR				
1,2	L-2-42	0-12	5L-	GLGLUSNP									
			SUM	an SBKS.P.	40"31				. 3				
			0		3								
					-								
					,								
				ž.									

Other Factors (.1946):

Site Classification (.1948): 🏲

Others Present:

Evaluated By:

Repair System

7812

Initial

System

250/0

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

short our standen RA)

PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North) 2