## HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION	
NAME WENdy HARMON PHO	ONE # <u>9/9-884-4013</u>
ADDRESS 158 CUM-Well M BENSON N.C.	
NAME OF MOBILE HOME PARK OR S/D Willow brook lat 13	
NAME OF OWNER (IF DIFFERENT)	
ADDRESS OF OWNER (IF DIFFERENT)	
PROPERTY LOCATION: STATE ROAD NAME AND # 50 58	BArleys XIIIS IZIS
The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If this system should malfunction, the owner is responsible for any necessary repairs.	
THIS INSPECTION IS VOID IF:  (1) the intended use of the septic system should change, and/or (2) the system should fail or malfunction, and/or (3) the owner or tenant of the property changes, and/or (4) after six months	FIS NOT FOR SALE PURPOSE POOL (Above GROUND) = 13-14 foot Away From DUATA LENES.
BUILDING MUST BE 5' FROM ANY PART OF SE  DO NOT DRIVE OR PARK ON SEPTIC SY	
STEEN STEEN BURGEREN DE STEEN BURGEREN BURGER BURG	MANAGAN SA MANAGAN SA
AUTHORIZATION OF EXISTING SYSTEM	
James & Manhant Trons	4-21-21
Signature of Inspector	Date