Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Description

System Type(s)

Site LTAR

Available Space (.1945)

Initial

System

Repair System

-25600 Sheet: Property ID: Lot #: File #:

Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Addres Propose Locatio Water S Evaluat	s: wire ed Facility: on of Site: Supply: tion Method f Wastewate	16×60 s	Date I Desig Prope ✓ Public In		Property Siz	e:	ner .	5-7-8 - Locata - Clear	More of Cot septic
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1,2,3	7	0-6	LS (A) Gr	VF/AS/AM/AND	248"	≥48°	_	_	PS .5
	≤ 22	6-12	LS Gr	VF/AS/AP/ASP					Charb
		12-48	sa sok	Frkikplsze					
					ř.				
	_					1 476			
						· ·			
						1 7	£"		
					4				
_							,v 3		
							1		
							100 4		

Other Factors (.1946):

Others Present:

Site Classification (.1948): PS A PEHS
Evaluated By:

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<b>GROUP</b>	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
L-LINEAR SLOPE FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-SLIGHTY STICKY S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	, E. F. E. F	SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY 0.4 - 0.1

EXPANSIVE

C-CLAY SC-SANDY CLAY

IV

