Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Owner:

Sheet: Property ID: Lot #: File #:

Code:

BNES 2105-0018

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

System

Available Space (.1945) System Type(s)

Site LTAR

Repair System

STE

Applicant: LITANOTIRALO

Location Water S Evaluation		: Auge	Date Desig Prope	Evaluated: 4-3.2 gn Flow (.1949): 36 grty Recorded: ndividual Wall Pit Industrial P	Vell	e:	er		
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)		DRPHOLOGY 1941 .1941 Consistence Mineralogy	PR .1942 Soil Wetness/ Color	OTHER OFILE FACTOR .1943 Soil Depth (IN.)	.1956 Sapro Class	Profile Class & LTAR	
1,2	1249	0-15				Deptii (iiv.)	Ciuss	Horiz	PS
3		15-40	5L 5CL	Anbrions An SSKS!	32-34" 2.1	yont !			, 3
Descrip	otion	In	itial Re	pair System	Other Factors (.1946):				

Other Factors (.1946): Site Classification (.1948): $\beta \le$

Evaluated By: Others Present:

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	1	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	П	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY 0.4 - 0.1

EXPANSIVE

C-CLAY SC-SANDY CLAY

IV

