HARNETT COUNTY HEALTH DEPARTMENT **ENVIRONMENTAL HEALTH** 307 CORNELIUS HARNETT BOULEVARD **LILLINGTON, NC 27546**

EXISTING SEPTIC SYSTEM INSPECTION

| NAME Jerry Pornds Construction INC PHO | ONE # 919 - 422-1175 |
|--|--|
| ADDRESS 5839 Elevation RD Benson N.C. 27509 | |
| NAME OF MOBILE HOME PARK OR S/D Cottlestone Box | 44tes |
| NAME OF OWNER (IF DIFFERENT) JEANNER BUllock | Pope |
| ADDRESS OF OWNER (IF DIFFERENT) 89 Galles CT Cox | HS N.C. 27821 |
| PROPERTY LOCATION: STATE ROAD NAME AND # 50. 2005 | Frickmin RD |
| PURPOSE OF INSPECTION: PURPOSE OF INSPECTION: | + STAINS AND LEST FOR H.C. |
| The aforementioned site has been evaluated by the Harnett Co Environmental Health Section. At the time of inspection, there system serving this site. If this system should malfunction, the any necessary repairs. | appeared to be a septic |
| THIS INSPECTION IS VOID IF: (1) the intended use of the septic system should change, and/or (2) the system should fail or malfunction, and/or (3) the owner or tenant of the property changes, and/or (4) after six months | -21 Spoke to owner About 3T under Concrete WAKENAY CUT OUTS FOR ACCESS TO TANK Were VISCOLE. IAN K AND LANGS UNDER Covered Pouch grapous Addition |
| BUILDING MUST BE 5' FROM ANY PART OF SE | PTIC SYSTEM |

DO NOT DRIVE OR PARK ON SEPTIC SYSTEM

| AUTHORIZATION OF EXISTING | SYSTEM |
|--|--------|
| Danes & Marshant TEHS | 9-2-2/ |
| Signature of Environmental Health Specialist | Date |
| | |