# RJB, P.E., P.A.

C-0269

### ROBERT J. BRACKEN ENGINEER + SURVEYOR

3768 Carbonton Road · Sanford, North Carolina 27330

December 21, 2021

Harnett County Inspections P.O. Box 65 Lillington, NC 27546

> REF: Slab Inspection Watson, Res. Briarwood Place Sanford, NC 27332 Harnett Co.

Dear Sir/ Madam.

I made an onsite visit to the site referenced above on December 14, 2021. The purpose of the visit was to examine a slab that had been placed for a storage building. At the time of my inspection a pre built shed building was in place. Because of the size and minimum amount of loading, I have no problem approving the slab for the existing building.

If you have any questions please feel free to call me at 919-774-6074.

Sincerely.

Robert J. Bracken, PE

1291

GINEE

## DESIGN PROFESSIONAL INSPECTION FORM

RECORD OF THE INSPECTION OF A **COMPONENT OR ELEMENT** BY A NC LICENSED ARCHITECT OR ENGINEER

Project Information:

| Residential Single-Family Project: 0    | Commercial Project: Y                |  |
|---|--------------------------------------|--|
| Code Enforcement Project No:            | Permit No:                           |  |
| Project Name:<br>Storage Shed           | Owner:<br>Kevin & Charlotte Watson   |  |
| Project Address:<br>285 Briarwood Place | Suite No:                            |  |
| Date Inspected: December 14, 20212      | Contractor Name: Kevin Watson, Owner |  |
| Component Inspected: Slab               | Tion valori, owner                   |  |

Responsible Licensed NC Architect or NC Engineer

| Name:            | Robert J Bracken PE                  |                      |  |
|------------------|--------------------------------------|----------------------|--|
| Firm Name:       | RJB,PE,PA                            |                      |  |
| Phone Numbers:   | Office: 919-774-6074                 | Mobile: 919-770 0809 |  |
| Email Address:   | bjbracken@windstream.net             |                      |  |
| Mailing Address: | 3768 Carbonton Rd, Sanford, NC 27330 |                      |  |

| APPLICABLE CODE: 2018 NCRC  |   |
|---|---|
| 2018 NCBC = 2018 NC Building Code; 2018 NCRC = 2018 NC Residential Code |   |
| Describe Element/Component/Type of Inspection: *                        | 8 |
| Slab for Storage Building   |   |
|   |   |

#### Attestation/Signature:

By signing below, I certify that the component and/or element of the building as identified on this form has been inspected by me or someone under my direct supervision per subsection (b2) of NC G.S. 153A-352 and is in compliance with the Code or other proposal of the architect or engineer for the project. This inspection is in compliance with all of the requirements of the above referenced

Code. Attach any additional documents if needed.

Licensed Architect or Engineer

12/21/2021

## Inspection Department disclaimer:

Upon the receipt of a signed written document as required under subsection (a) of Article 160A-413.5., Code Enforcement shall be discharged and released from any liabilities, duties and responsibilities imposed by this article or in common law from any claim arising out of or attributed to the component or element in the construction of the building for which the signed written document was submitted. Be aware that this inspection will be noted in all inspection records including the Certificate of Occupancy or Certificate of Compliance. This inspection does not address any local ordinances or zoning requirements.

<sup>\*(</sup>subgrade form/letter may also be required)