Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

IOI OIL SILE WILDIE	THE STATE OF		
Owner: Campbell Applicant: Address: 95 Drogen Fly L			
Address: 95 Dragon Fly La	Date Evaluated: /2-12-21		
Proposed Facility: 3FD	Design Flow (.1949): 360 GPD	Property Size:	
Location of Site:	Property Recorded:		
	Public Individual Well	☐ Spring	Other
Evaluation Method: Auger Bo	oring Pit Cut		
Type of Wastewater:	Sewage Industrial Process	☐ Mixed	

O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941			OTHER PROFILE FACTORS				
			.1941 Structure/ Texture		.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
2	L	0-15	W	G-	Folus/welase	>48"	248"	_	_	Ps. 4
	5-7%	15-48	Sc1	SBh	Films/melmal					& LTAR PS. U
					,		4			
		3				v * s	= 6			
						×	a.v			
						; ÷				
						•				

Description	Initial	Repair System	Other Factors (.1946):
	System		Site Classification (.1948):
Available Space (.1945)	-		Evaluated By: MREHS
System Type(s)	25%,10	25% 120	Others Present:
Site LTAR	.4	. 4	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	5	SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

0.4 - 0.1

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY

PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY

EXPANSIVE

C-CLAY SC-SANDY CLAY

IV

Dragon Fly La