



Harnett County
420 McKinney Pkwy
LILLINGTON, NC 27546
Phone:
Fax:

9/23/2022

**SUBJECT: BRES2202-0050
BUILDING RESIDENTIAL**

To: Michael Baxter

Here are the results of all Inspections located at **115 MOSSBURG CT:**

Inspection Type: FINAL**
Scheduled Date/Time:
Completed Date/Time:
Inspector: Slade Burton Lawson III
Result:
Remarks:
Notes:

Inspection Type: ZONING
Scheduled Date/Time:
Completed Date/Time:
Inspector: Planning Bucket
Result:
Remarks:
Notes:

Inspection Type: ELECTRICAL UNDERGROUND
Scheduled Date/Time:
Completed Date/Time:
Inspector: James T Hall
Result:
Remarks: eTRAKiT Inspection Request
Notes:

Inspection Type: BONDING
Scheduled Date/Time:
Completed Date/Time:
Inspector: James T Hall
Result:
Remarks: eTRAKiT Inspection Request
Notes:



Harnett County
420 McKinney Pkwy

LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: ELECTRICAL UNDERGROUND
Scheduled Date/Time: 9/23/2022
Completed Date/Time: 9/23/2022
Inspector: James T Hall
Result: DISAPPROVED
Remarks: eTRAKiT Inspection Request
Notes: 9/21/2022 3:59 PM Michael Baxter

Contact Name: Michael Baxter
Site Address: 115 MOSSBURG CT
Phone: 9104315024
e-Mail: mikebaxter71@gmail.com

Bonding around the pool doesn't meet the code needs to be 18" to 24" from water edge 4" to 6" under ground and connected to metal parts in 4 places with 8 awg copper.

Inspection Type: BONDING
Scheduled Date/Time: 9/23/2022
Completed Date/Time: 9/23/2022
Inspector: James T Hall
Result: DISAPPROVED
Remarks: eTRAKiT Inspection Request
Notes: 9/21/2022 3:59 PM Michael Baxter

Contact Name: Michael Baxter
Site Address: 115 MOSSBURG CT
Phone: 9104315024
e-Mail: mikebaxter71@gmail.com

Bonding around the pool doesn't meet the code needs to be 18" to 24" from water edge 4" to 6" under ground and connected to metal parts in 4 places with 8 awg copper.