

Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

11/13/2024

SUBJECT: BRES2203-0057

BUILDING RESIDENTIAL

To: CRUZ GABRIEL CABRERA

Here are the results of all Inspections located at **1861 US 401 S**:

Inspection Type: MONO SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: UNDER SLAB TRADES

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: FINAL**

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:





420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: 9/12/2023
Completed Date/Time: 9/12/2023
Inspector: Oliver Tolksdorf
Result: APPROVED

Remarks: Notes:

Inspection Type: FOOTING
Scheduled Date/Time: 9/29/2023
Completed Date/Time: 9/29/2023

Inspector: John B Kokoszka Result: DISAPPROVED

Remarks:

Notes: Inspector JTH changed the inspection assignment from JTH to JBK

No plans on site

Inspection Type: FOOTING
Scheduled Date/Time: 10/4/2023
Completed Date/Time: 10/4/2023
Inspector: James T Hall
Result: DISAPPROVED

Remarks:

Notes: 1. Footing needs to be under existing footing on each corner of house 1' for continuous

footing2. Need to support Reid bar 3" from bottom of footing and extend Reid bar under each

corner of house

Inspection Type: FOOTING
Scheduled Date/Time: 10/10/2023
Completed Date/Time: 10/10/2023
Inspector: James T Hall
Result: APPROVED

Remarks:

Notes: Inspector SPG changed the inspection assignment from SPG to JTH

Inspection Type: FOUNDATION
Scheduled Date/Time: 10/26/2023
Completed Date/Time: 10/26/2023
Inspector: John B Kokoszka
Result: APPROVED

Remarks:

Notes: Inspector JTH changed the inspection assignment from JTH to JBK



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: OPEN FLOOR
Scheduled Date/Time: 11/2/2023
Completed Date/Time: 11/2/2023
Inspector: John B Kokoszka
Result: DISAPPROVED

Remarks:

Notes: Need to have 18" from the bottom of joist to dirt. Or needs to be treated wood

Inspection Type: OPEN FLOOR
Scheduled Date/Time: 11/6/2023
Completed Date/Time: 11/6/2023
Inspector: Daniel L Floyd
Result: APPROVED

Remarks: Notes:

Inspection Type: ROUGH IN
Scheduled Date/Time: 3/1/2024
Completed Date/Time: 3/1/2024
Inspector: James T Hall
Result: FAIL W/ PENALTY

Remarks:

Notes:

Missing 2-2x10 header over door at laundry roomMissing nails in hurricane strap over back doorMissing hurricane strap and nails in hurricane straps on back wall in bedroomInsulation bafflesFire caulk refrigerant lines on end wall in bedroomMissing air barrier on wall over old roof up to top plate, behind tub and in chase at end of tubMissing nailer to nail tub surroundFire caulk all holes and wires through top and bottom platesNeed to seal around tub drainNeed 3' head of water on drain line testNeed 100 psi on water line test had 77 psiNeed 2' walkway to AHU in atticRafter can not be wider than ridge beamHeal of rafter needs to bare solid on 2x on roof in atticPlumbing vent in attic needs to go 6" above ew roofRed light and receptacle at AHU in atticNeed smoke detector inside front bedroom and combo smoke and carbon outside bedroom and they need to all be interconnectedCrawl space access needs to be 18" x24" per code



Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 3/5/2024
Completed Date/Time: 3/5/2024
Inspector: James T Hall
Result: FAIL W/ PENALTY

Remarks:

Notes:

Insulation bafflesFire caulk refrigerant lines on end wall in bedroomMissing air barrier on wall over old roof up to top plate, behind tub and in chase at end of tubNeed 100 psi on water line test had 44 psiRafter can not be wider than ridge beamHeal of rafter needs to bare solid on 2x on roof in atticPlumbing vent in attic needs to go 6" above ew roofNeed light and receptacle at AHU in atticNeed smoke detector inside front bedroom and combo smoke and carbon outside bedroom and they need to all be interconnectedCrawl space access needs to be 18" x24" per

code

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 3/11/2024
Completed Date/Time: 3/11/2024
Inspector: John B Kokoszka
Result: DISAPPROVED

Remarks:

Notes:

Floor Joist not bearing at crawl space door

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: 3/14/2024
Completed Date/Time: 3/14/2024
Inspector: Daniel L Floyd
Result: APPROVED

Remarks:

Notes: Items from the previous inspection were completed

Inspection Type: INSULATION
Scheduled Date/Time: 3/18/2024
Completed Date/Time: 3/18/2024
Inspector: John B Kokoszka
Result: APPROVED

Remarks: Notes:



Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FINAL** Scheduled Date/Time: 7/17/2024 Completed Date/Time: 7/17/2024 Inspector: John B Kokoszka Result: **CANCELLED**

Remarks:

Notes: Inspector SPG changed the inspection assignment from SPG to JBK

> not ready 1. Need ladder for attic access2. Missing expansion tank on hot water heater3. Need to seal around toilet4. Need to seal around sink drain in bathroom5. Missing rear steps6. Need to sell sleeve at sewer line7. Need to get the sewer line inspected before finals8. Crawlspace access 18 x 249. Sewer line needs to be in beddeddidn't look in crawlspace because it's full of dirt. Need to call in sewer lines inspection before final. Need to do complete final inspection on

the addition. just noticed a couple of things

Inspection Type: **UNDER SLAB TRADES**

Scheduled Date/Time: 7/31/2024 Completed Date/Time: 7/31/2024 Inspector: James T Hall Result: DISAPPROVED

Remarks:

Notes: No under slab plumbing here

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: 8/2/2024 Completed Date/Time: 8/2/2024

John B Kokoszka Inspector: **DISAPPROVED** Result:

Remarks:

Notes:

fire 5 ft

The slope of the sewer needs to drain the tank. The slope is drain back to the house within the

Inspection Type: **SEWER CONNECTION**

Scheduled Date/Time: 8/14/2024 Completed Date/Time: 8/14/2024 Inspector: James T Hall Result: DISAPPROVED

Remarks:

Notes: Need sweep fitting at cleanout not T fittingBed pipe per codeNeed correct pipe 1 section of

pipe has no label on it



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: 10/1/2024
Completed Date/Time: 10/1/2024
Inspector: James T Hall
Result: DISAPPROVED

Remarks:

Notes: Bed pipe per code ditch full of water Missing cleanouts per code

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: 10/9/2024 Completed Date/Time: 10/9/2024 Inspector: James T Hall Result: APPROVED

Remarks: Notes:

Inspection Type: FINAL**
Scheduled Date/Time: 10/11/2024
Completed Date/Time: 10/18/2024
Inspector: Deen Taylor
Result: DISAPPROVED

Remarks:

Notes: Unable to locate expansion tank

Inspection Type: FINAL**
Scheduled Date/Time: 10/29/2024
Completed Date/Time: 10/29/2024
Inspector: James T Hall
Result: DISAPPROVED

Remarks:

Notes: Inspector JBK changed the inspection assignment from JBK to JTH

House locked

Inspection Type: FINAL**
Scheduled Date/Time: 10/31/2024
Completed Date/Time: 10/31/2024
Inspector: Picardo D Hor

Inspector: Ricardo D Honrada Result: DISAPPROVED

Remarks:

Notes: Customer said the house is not occupied & the back door will be unlocked.

Need to pass the failed inspection mechanical, electrical and plumbing.



420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: FINAL**
Scheduled Date/Time: 11/13/2024
Completed Date/Time: 11/13/2024
Inspector: Daniel L Floyd
Result: FAIL W/ PENALTY

Remarks:

Notes:

Inspector JBK changed the inspection assignment from JBK to DLF

All items must be corrected to pass final