Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Towns Poe Applicant: Address: \$777 Thoms for and Date Evaluated: 5-8-22 Proposed Facility: \$FD Design Flow (.1949): \$360 Property Size: Location of Site: Property Recorded: Water Supply: Public Individual Well Spring Other Evaluation Method: Auger Boring Pit Cut Type of Wastewater: Sewage Industrial Process Mixed												
P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS .1942				De Silv			
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR			
1,2	L	0-12	US Gr		10 YR 6/1	>48"	_	_	B.4			
	2-56	12-8	sci sok	Filsskelske	276				Group			
				177.7.	=	196						
	1						4					
									'A			
						1			1			
						- Ta						
	£1											
				1		7	-					
				-								
								I.				

Other Factors (.1946):
Site Classification (.1948):
Evaluated By:

Others Present:

Repair System

.4

FUMP TO 25% 120

Initial

System

Description

Available Space (.1945) System Type(s) Site LTAR

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	Ĭ	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM	S-STICKY VS-VERY STICKY
H-HEAD SLOPE CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3	EFI-EXTREMELY FIRM	NP-NON-PLASTIC SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

SIC-SILTY CLAY 0.4 - 0.1

SC-SANDY CLAY STRUCTURE MINERALOGY SLIGHTLY EXPANSIVE

IV

EXPANSIVE

C-CLAY

SG-SINGLE GRAIN M- MASSIVE CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

