HTE#: <u>BORS</u> 2206-0037

## HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

## **EXISTING SEPTIC SYSTEM INSPECTION**

Name: Althour Maria Phone # 1	
Name	119 303 - 4836
Name: Anthony Moore Phone #: Address: 724 Calvary CHURCH RD Sant	and N.C. 27332
Name of Mobile Home Park or S/D:	
Name of Owner (if different):	
Address of Owner (if different):	
Property Location (State Road name and #): 5/1705 Coll	Vany CAURCH RD
Purpose of Inspection: 26x71 Putato metal BIDE	5
The aforementioned site has been evaluated by the Harnett C Environmental Health Section. At the time of inspection, the system serving this site. If the system should malfunction, the	re appeared to be a septic
	o o marcine and a composition of
necessary repairs.	DECK ADDETION ON TOP
	*DECK ADDITION ON TOP Of Sephil System.
THIS INSPECTION IS VOID IF:  1. the intended use of the septic system should change, and/	DECK ADDITION ON TOP OF Septil System.
necessary repairs.  THIS INSPECTION IS VOID IF:  1. the intended use of the septic system should change, and/ 2. the system should fail or malfunction, and/or	DECK ADDITION ON TOP OF Septil System.
THIS INSPECTION IS VOID IF:  1. the intended use of the septic system should change, and/	DECK ADDITION ON TOP OF Septil System.
THIS INSPECTION IS VOID IF:  1. the intended use of the septic system should change, and/ 2. the system should fail or malfunction, and/or 3. the owner or tenant of the property change, and/or	DECK ADDITION ON TOP of Septil System.
necessary repairs.  THIS INSPECTION IS VOID IF:  1. the intended use of the septic system should change, and/2. the system should fail or malfunction, and/or 3. the owner or tenant of the property change, and/or 4. after six months  BUILDING MUST BE 5' FROM ANY PART (	OF SEPTIC SYSTEM  OF SYSTEM