

November 16, 2022

Brian Culver Triangle Home Pros 6312 Lauraca Lane Fuquay Varina, NC 27526

RE: 16 Timber Rail Lane Holly Springs, North Carolina Pool Pavilion footing inspection

Dear Mr. Culver:

A site visit was made to the above referenced address to perform an open footing inspection for the pool house structure prior to the placement of concrete. The turned down perimeter footing around the enclosed area, 30" diameter x 42" deep post footings and pavilion slab were prepared in accordance with the engineered drawings. 6 mil vapor barrier on 4" crushed stone on firm clean soil was installed below all concrete slab areas. The footing preparation was completed per plan and is adequate to support the concrete footings and slab.

Please call me if you have any questions.

Sincerely,

J. Smith Structural Engineering, PLLC

Jacob E. Smith, P.E. Owner



1532 CONE AVE. APEX, NC 27502 919.864.1430 jsmithstructural@gmail.com