



# Permit Inspections Harnett County

**Permit Number: BRES2211-0002**

Description: **2 story garage**

Applied: **11/1/2022**

Approved: **1/9/2023**

Site Address: **4001 TRAVERSE DR**

Issued: **1/9/2023**

Finalled:

City, State Zip Code: **FUQUAY-VARINA, NC 27526**

Status: **ISSUED**

Applicant: **GRIFFITH JOHNNY**

Parent Permit:

Owner: **MCKOY FRANKIE L**

Parent Project:

Contractor: **JOHLCO CONTRACTING**

Details:

### LIST OF INSPECTIONS

SEQ ID	SCHEDULED DATE	COMPLETED DATE	TYPE	INSPECTOR	RESULT	REMARKS
			FOUNDATION	Justin Ryan McLeod		
Notes:						
			MONO SLAB	Justin Ryan McLeod		
Notes:						
			FINAL**	Justin Ryan McLeod		
Notes:						
	1/25/2023	1/25/2023	FOOTING	Justin Ryan McLeod	DISAPPROVED	
Notes: Footing must be continuous or have properly designed spread (lug) footing at each side of garage door.						
	1/26/2023	1/26/2023	FOOTING	Justin Ryan McLeod	APPROVED	
Notes:						
	1/31/2023	1/31/2023	UNDER SLAB TRADES	Scott Guy	APPROVED	
Notes: plumbing						
	4/14/2023	4/14/2023	ROUGH IN	Justin Ryan McLeod	DISAPPROVED	
Notes: Anchor bolt left of man door under hand switch area.						
	4/20/2023	4/20/2023	ROUGH IN REINSPECT	John B Kokoszka	APPROVED	
Notes:						





# Permit Inspections Harnett County

	4/27/2023	4/27/2023	INSULATION	Justin Ryan McLeod	APPROVED	
--	-----------	-----------	------------	--------------------	----------	--

Notes:  
Inspector TSG changed the inspection assignment from TSG to JRM

	4/27/2023	4/27/2023	SLAB	Justin Ryan McLeod	APPROVED	
--	-----------	-----------	------	--------------------	----------	--

Notes:  
This was not approved in system customer advised still opened rough in was approved 4/20  
Inspector TSG changed the inspection assignment from TSG to JRM  
This was seen under "footing inspection"

	12/11/2023	12/11/2023	FINAL**	Justin Ryan McLeod	DISAPPROVED	
--	------------	------------	---------	--------------------	-------------	--

Notes:  
1. Handrail at steps. 2. door knobs. 3. Shower door or curtain at shower, (must have a way to contain water in shower). 4. Step into garage cannot be higher than 8-1/4 inches. 5. Grade not sloped away from building at mini split. 6. Cannot locate attic access. 7. Must have exterior rated door separating garage from stairs because you cannot egress from habitat space through garage. Plans show this door on it

