Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

## SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Water S Evalua	Ely Ely ed Facility: on of Site: Supply: tion Method f Wastewate	: Auge	Prope Prope	rty Recorded: adividual W	☐ Cut	e:	er			
P R O F	.1940		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
L E #	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
l	4	0-14	W Gr	VFI/W/we/wa	> 104R 7/2 ≥ 40°	> 48"		_	PS. 5	
	2-5%	14-48	sci SBL	VFI /w/we/wa					711	
				7-17-1220						
							11			
								7		
								Programme and the second		
				1.5						
							Ť.			
				1			1.4			
			,		()					
					7					

Other Factors (.1946):

Other Factors (.1946):
Site Classification (.1948):

Evaluated By:
Others Present:

Repair System

Initial System

Description

Available Space (.1945) System Type(s) Site LTAR

COMMENTS: \_\_\_\_

LANDSCAPE POSITIONS	<b>GROUP</b>	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE	I	S-SAND	1.2 - 0.8		1977
S-SHOULDER SLOPE		LS-LOAMY SAND		VFR-VERY FRIABLE	NS-NON-STICKY
L-LINEAR SLOPE				FR-FRIABLE	SS-SLIGHTY STICKY
FS-FOOT SLOPE	II	SL-SANDY LOAM	0.8 - 0.6	FI-FIRM	S-STICKY
N-NOSE SLOPE		L-LOAM		VFI-VERY FIRM	VS-VERY STICKY
H-HEAD SLOPE				EFI-EXTREMELY FIRM	NP-NON-PLASTIC
CC-CONCLAVE SLOPE	III	SI-SILT	0.6 - 0.3		SP-SLIGHTLY STICKY
CV-CONVEX SLOPE		SIL-SILT LOAM			P-PLASTIC
T-TERRACE		CL-CLAY LOAM			VP-VERY PLASTIC
FP-FLOOD PLAN		SCL-SANDY CLAY LOAM			

IV SIC-SILTY CLAY 0.4 - 0.1 C-CLAY

SC-SANDY CLAY

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB **GR-GRANULAR** SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE EXPANSIVE

PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North) 70 1 40'Exiring (5'wide but)

To Pine Wood