Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: Applicant:
Address: 5-20 Treebale Date Evaluated: 4/6/13

Proposed Facility: Property Recorded:

Water Supply: Public Individual Well Spring Other

Evaluation Method: Auger Boring Pit Cut

Type of Wastewater: Sewage Industrial Process Mixed

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS .1942					
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
423	4,55 5%	0-12	GYLS	VFL, NS NP SEX	$\overline{}$	_	$\widehat{}$	_	PS.	
		32-49	SAMSCL	VFL, NS, NP, Sex		48"		_	PS. 0.5	

Description	Initial	Repair System	
	System		Sit
Available Space (.1945)	1	8	
System Type(s)	~	T	
Site LTAR	6.5	0.5	

Other Factors (.1946): Site Classification (.1948): Evaluated By: Others Present:

PS. MR DEHS

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	S-SAND LS-LOAMY SAND SL-SANDY LOAM L-LOAM	1.2 - 0.8 0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

0.4 - 0.1

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY

EXPANSIVE

C-CLAY SC-SANDY CLAY

IV

PR-PRISMATIC

Show profile locations and other site features (dimensions, references or benchmark, and North)

A second of the state of

Treebank