Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Applicant:

wner:

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Location	sed Facility:		Lm Desig	Evaluated: gn Flow (.1949): 30 erty Recorded: ndividual	Vell	g 🔲 Oth	er		
P R O F I	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS				
L E #			.1941 Structure/ Texture	.1941 Consistence Mineralogy	Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
)	02 73	0-12	S 52	182 ms/2					
		12-32	53 K.SCL	180091 18 25 AF					P54
2		0-6	S 5 L	venaslae					
		6-26	SBXSL	m solx					PS (15
		26	8 20						
								-	
3		0-12	GSL	VER N3/49 FR 55/2					
		12-34	SBKSKL	masix					P5,7
escription Initial Repair System System Available Space (.1945)					Other Factors (.1946): Site Classification (.1948): Evaluated By:				
System	Type(s)		250600	(PURP)	Others Present:				
Site LT			2	.4					

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE	NS-NON-STICKY
L-LINEAR SLOPE		LS-LOWIT SAILD		FR-FRIABLE	SS-SLIGHTY STICKY
FS-FOOT SLOPE	II	SL-SANDY LOAM	0.8 - 0.6	FI-FIRM	S-STICKY
N-NOSE SLOPE		L-LOAM		VFI-VERY FIRM	VS-VERY STICKY
H-HEAD SLOPE				EFI-EXTREMELY FIRM	NP-NON-PLASTIC
CC-CONCLAVE SLOPE	III	SI-SILT	0.6 - 0.3		SP-SLIGHTLY STICKY
CV-CONVEX SLOPE		SIL-SILT LOAM			P-PLASTIC
T-TERRACE		CL-CLAY LOAM			VP-VERY PLASTIC
FP-FLOOD PLAN		SCL-SANDY CLAY LOAM			

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SC-SANDY CLAY

SIC-SILTY CLAY 0.4 - 0.1

EXPANSIVE

C-CLAY

IV

