HTE# BRES 2304-0057

## HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

## **EXISTING SEPTIC SYSTEM INSPECTION**

NAME Joseph + Beverly Creech PHONE #
ADDRESS 815 MESSELLY CREECH PHONE # ADDRESS 815 MESSELLS BENSON NC 27504
NAME OF MOBILE HOME PARK OR S/D
NAME OF OWNER (IF DIFFERENT)
ADDRESS OF OWNER (IF DIFFERENT)
PROPERTY LOCATION: STATE ROAD NAME AND # 50 1708 Maller PD
PURPOSE OF INSPECTION: 40 X 60 Metal Butleton.  The aforementioned site has been evaluated by the Harnett County Health Department
The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If this system should malfunction, the owner is responsible for any necessary repairs.
THIS INSPECTION IS VOID IF: (1) the intended use of the septic system should change, and/or (2) the system should fail or malfunction, and/or (3) the owner or tenant of the property changes, and/or (4) after six months
BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM DO NOT DRIVE OR PARK ON SEPTIC SYSTEM
THE SECTION OF SECTION
AUTHORIZATION OF EXISTING SYSTEM
MANNAN 5-10-23
Signature of Environmental Health Specialist Date