

HTE #: BZES2305-0006

HARNETT COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH
307 CORNELIUS HARNETT BOULEVARD
LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

Name: JONATHAN FAIRBROTHER Phone #: 843-327-4974

Address: 3100 Gold Dust Ln Willow Springs NC 27572

Name of Mobile Home Park or S/D: _____

Name of Owner (if different): Melissa Mason

Address of Owner (if different): 252 Bennett Rd Coats N.C. 27521

Property Location (State Road name and #): on 2010 Bennett Rd

Purpose of Inspection: Replace SWMH with DMWH 32'x66' 3/8" DIA

The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs.

THIS INSPECTION IS VOID IF:

1. the intended use of the septic system should change, and/or
2. the system should fail or malfunction, and/or
3. the owner or tenant of the property change, and/or
4. after six months

**BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM
DO NOT DRIVE OR PARK ON SEPTIC SYSTEM**

AUTHORIZATION OF EXISTING SYSTEM

James E. Manhart ^{IP 12/6/15}
Signature of Environmental Health Specialist

5-17-23
Date