HTE #: BRES 2305 -0018

HARNETT COUNTY HEALTH DEPARTMENT ENVIRONMENTAL HEALTH 307 CORNELIUS HARNETT BOULEVARD LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

Name: <u>GANG Clackness</u> Phone #: <u>1-815-558-0</u> Address: <u>1321 Cobb 12D Benson N.C. 27504</u>	039
Address: 1321 Cobb 12D Benson N.C. 27504	
Name of Mobile Home Park or S/D:	
Name of Owner (if different):	
Address of Owner (if different):	
Property Location (State Road name and #): 52/556 666 RD	
Purpose of Inspection: 24x25 Garage - metal	
The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs.	
 the intended use of the septic system should change, and/or the system should fail or malfunction, and/or the owner or tenant of the property change, and/or after six months 	
BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM DO NOT DRIVE OR PARK ON SEPTIC SYSTEM	
AUTHORIZATION OF EXISTING SYSTEM	
James & Manhan J 2543	15-23
Signature of Environmental Health Specialist	Date