

LILLINGTON,NC 27546 Phone: Fax:

## 4/29/2024

## SUBJECT: BRES2307-0069 BUILDING RESIDENTIAL

To: MCNEILL JOHN W

Here are the results of all Inspections located at 5019 TITAN ROBERTS RD:

Inspection Type:	FOOTING
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	FOUNDATION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	MONO SLAB
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	SLAB
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	





LILLINGTON,NC 27546 Phone: Fax:

Inspection Type:	UNDER SLAB TRADES
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	
Notes:	

Inspection Type:	INSULATION REINSPECTION
Scheduled Date/Time:	
Completed Date/Time:	
Inspector:	Steven Gazlay
Result:	
Remarks:	eTRAKiT Inspection Request
Notes:	

Inspection Type:	ROUGH IN
Scheduled Date/Time:	10/12/2023
Completed Date/Time:	10/12/2023
Inspector:	John B Kokoszka
Result:	DISAPPROVED
Remarks:	
Notes:	House was locked at the time of inspection
Increation Type	

Inspection Type:	ROUGH IN REINSPECT
Scheduled Date/Time:	10/16/2023
Completed Date/Time:	10/16/2023
Inspector:	James T Hall
Result:	DISAPPROVED
Remarks:	
Notes:	lock box code 9997

Need engineers letter for repairs on all floors and inspector needs to know where damage was in house since repairs have been done

Need engineers letter for repairs on all floors and inspector needs to know where damage was in house since repairs have been done





Notes:

Harnett County 420 Mckinney Pkwy

LILLINGTON,NC 27546 Phone: Fax:

Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks:	1/25/2024
Notes:	1/23/2024 11:23 AM Paul Judson lockbox: 9997 Contact Name: Paul Judson Site Address: 5019 TITAN ROBERTS RD Phone: 2526718118 e-Mail: ncadmin@dswhomes.com
	1/23/2024 11:28 AM Paul Judson lockbox: 9997 Contact Name: Paul Judson Site Address: 5019 TITAN ROBERTS RD Phone: 2526718118 e-Mail: ncadmin@dswhomes.com
Inspection Type: Scheduled Date/Time: Completed Date/Time: Inspector: Result: Remarks:	ROUGH IN REINSPECT 1/31/2024

1/30/2024 1:33 PM Paul Judson Lockbox: 9997 Per Permitting tech request AM Contact Name: Paul Judson Site Address: 5019 TITAN ROBERTS RD Phone: 2526718118 e-Mail: ncadmin@dswhomes.com

Cut exterior block wall for new shower stall and non treated lumber in contact with masonry . Need engineer letter.Need plumbing drain test.Need to remove a section of floor in kitchen to see if any structural work has been done





LILLINGTON,NC 27546 Phone: Fax:

Inspection Type:	ROUGH IN REINSPECT
Scheduled Date/Time:	2/19/2024
Completed Date/Time:	2/19/2024
Inspector:	James T Hall
Result:	APPROVED
Remarks:	eTRAKiT Inspection Request
Notes:	Per engineer letter

Inspection Type:	INSULATION
Scheduled Date/Time:	3/20/2024
Completed Date/Time:	3/20/2024
Inspector:	John B Kokoszka
Result:	DISAPPROVED
Remarks:	eTRAKiT Inspection Request
Notes:	3/18/2024 12·14 PM Derrick Am

3/18/2024 12:14 PM Derrick Amis

Contact Name: Derrick Amis Site Address: 5019 TITAN ROBERTS RD Phone: 9105749743 e-Mail: derrick.amis@dswhomes.com

Need to correct insulation in the floor system.but need to remove all floor insulation and flooring and call in an open floor because of the new flor joist installed.No flashing, some not bearing , need to make sure there is 18" from soil for non treated lumber

Inspection Type:	INSULATION SFD MONO
Scheduled Date/Time:	3/21/2024
Completed Date/Time:	3/21/2024
Inspector:	John B Kokoszka
Result:	DISAPPROVED
Remarks:	
Notes:	Remove all insulation. There was some of the floor joists replace and not inspected. I saw a few non treated joist in contact with masonry. I noticed one joist floating on a 2x4 laying on its side.



## LILLINGTON,NC 27546 Phone: Fax:

Inspection Type:	OPEN FLOOR
Scheduled Date/Time:	3/26/2024
Completed Date/Time:	3/26/2024
Inspector:	John B Kokoszka
Result:	APPROVED
Remarks:	eTRAKiT Inspection Request
Notes:	3/20/2024 10:30 AM Derrick Amis

Contact Name: Derrick Amis Site Address: 5019 TITAN ROBERTS RD Phone: 9105749743 e-Mail: derrick.amis@dswhomes.com

3/25/2024 8:36 AM Derrick Amis

Contact Name: Derrick Amis Site Address: 5019 TITAN ROBERTS RD Phone: 9105749743 e-Mail: derrick.amis@dswhomes.com

Inspection Type:	INSULATION SFD MONO
Scheduled Date/Time:	3/27/2024
Completed Date/Time:	3/27/2024
Inspector:	John B Kokoszka
Result:	APPROVED
Remarks:	eTRAKiT Inspection Request
Notes:	3/26/2024 12:13 PM Derrick Amis

Contact Name: Derrick Amis Site Address: 5019 TITAN ROBERTS RD Phone: 9105749743 e-Mail: derrick.amis@dswhomes.com



Harnett NORTH CAROLINA

Harnett County 420 Mckinney Pkwy

LILLINGTON,NC 27546 Phone: Fax:

Inspection Type:	FINAL**
Scheduled Date/Time:	4/23/2024
Completed Date/Time:	4/23/2024
Inspector:	James T Hall
Result:	APPROVED
Remarks:	eTRAKiT Inspection Request
Notes:	4/19/2024 10:54 AM Derrick Amis

Contact Name: Derrick Amis Site Address: 5019 TITAN ROBERTS RD Phone: 9105749743 e-Mail: derrick.amis@dswhomes.com

