

Joe E Godwin Sr. , P.E., P.L.S.

Jason E Godwin , P.L.S.

ENOCH
ENGINEERS, P.A.
1403 NC Highway 50 South
Benson, North Carolina 27504
919.894.7765

Email: general@enochengineers.com

www.enochengineers.com

MATERIALS & TEST DIVISION

FIELD REPORT

PROJECT

CLIENT: FISHER BUILD GROUP	DATE: 11.2.23
PROJECT: RESI ADDITION FOOTING	CONTRACTOR: D. FISHER
ADDRESS: 254 OAK VALLEY FARM R	TECHNICIAN: BH
LOT #: BRES2308-0040	

TEST SUMMARY

PERFORMED FOOTING PROJECTION EVALUATION OF SITE NOTED ABOVE. THE CONCRETE FOOTING IN THE 4 FOOT SECTION OF RIGHT/FRONT CORNER BY PATIO HAS BEEN DETERMINED TO ADEQUATELY SUPPORT THE CMU FOUNDATION LOAD APPLIED. NO ADDITIONAL REPAIRS OR RECOMMENDATIONS ISSUED. SOIL BEARING 2000PSF THROUGHOUT.

TESTING RESULTS

SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %

RETURN VISIT REQUIRED

YES

NO

TECHNICIAN:



Disclaimer:

Soils & Material inspections, testing results and on-site determinations contained in this report become void after 30 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.