## Harnett County Inspections DEPARTMENT

## 3<sup>RD</sup> PARTY INSPECTION FORM

RECORD OF THE INSPECTION OF A **COMPONENT OR ELEMENT** BY A NC LICENSED ARCHITECT OR ENGINEER

	ommercial Project: Y N
Project Address: 140 Oxfordshire Dr, Fugrey-Voning	wner: Amanda Juranic uite No.:
Date Inspected: 7/17/2023  Component Inspected: Foundation, Framing	ontractor Name: Kvstom Restoration
Responsible Licensed NC Architect or NC Engineer Name: Patrick Kurtz	•
Phone No.: Office 919-548-0978  Email Address: in fo@ JD5consulting.net	10bile 919 - 480 - 1075
Mailing Address: 543 Pylon Dr, Raleigh NC, 27606  Applicable Code Section:	
2018 NCBC = 2018 NC Building Code; 2018 NCRC = 2018 NC Residential Code	
Describe Element/Component/Type of Inspection: * spection of damage occurring at the right side of the garage at the front elevation. Framing was exposed on the interior.	
*(subgrade form/letter may also be required) Attestation/Si By signing below, I certify that the component and/or eleme as identified on this form has been inspected by me or someon supervision per subsection (b2) of NC G.S. 153A-352 and is in the Code or other proposal of the architect or engineer for inspection is in compliance with all of the requirements of the Code. Attach any additional documents if needed.	ent of the building ne under my direct compliance with or the project. This
LICENSED ARCHITECT OR ENGINEER Thamas	hale SEAL

Inspection Department disclaimer: