Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section Sheet: Property ID: Lot #: File #:

Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Clayton Homes
Owner:
Address: 905 Pina Och
Proposed Facility: Dwm H Date Evaluated: //- 28-23 Design Flow (.1949): 480 GPD Property Size: Location of Site: Property Recorded: Public Individual Water Supply: ☐ Spring Other Evaluation Method: Auger Boring ☐ Pit Cut ☐ Industrial Process Type of Wastewater: Sewage ☐ Mixed

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (In.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR	
1,2	L	0-40	25	VFT/NSP/NSP	> 48"	>48"	_	_	S	.8
	L 5-7%	40-48	SL	VF-/NSP/NXP						
										+

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)	System	~	Site Classification (.1948): Evaluated By:
System Type(s)			Others Present: 0.7.
Site LTAR	. 8	-8	0.7.

COMMENTS: ____

LANDSCAPE POSITIONS	<u>GROUP</u>	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

SIC-SILTY CLAY 0.4 - 0.1 IV C-CLAY

SC-SANDY CLAY

MINERALOGY SLIGHTLY EXPANSIVE

EXPANSIVE

STRUCTURE SG-SINGLE GRAIN M- MASSIVE CR-CRUMB

GR-GRANULAR SBK-SUBANGULAR BLOCKY

ABK-ANGULAR BLOCKY

PL-PLATY PR-PRISMATIC Show profile locations and other site features (dimensions, references or benchmark, and North) 2 16 160

Pine Oak