



Harnett County
420 McKinney Pkwy
LILLINGTON, NC 27546
Phone:
Fax:

12/19/2024

SUBJECT: BRES2312-0352
BUILDING RESIDENTIAL

To: ROSALES MARIA

Here are the results of all Inspections located at **76 MARKS RD:**

Inspection Type: SEWER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: WATER CONNECTION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: MFH FINAL**
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: ZONING
Scheduled Date/Time:
Completed Date/Time:
Inspector: Planning Bucket
Result:
Remarks:
Notes:





Harnett County
420 McKinney Pkwy

LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: FOOTING
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks: eTRAKiT Inspection Request
Notes: 6/18/2024 1:53 PM RAVEN ROCK MOBILE HOME MOVER

Contact Name: RAVEN ROCK MOBILE HOME MOVER
Site Address: 76 MARKS RD
Phone: 9197753600
e-Mail: Crubio201@gmail.com

Inspection Type: ADDRESS
Scheduled Date/Time: 4/15/2024
Completed Date/Time: 4/15/2024
Inspector: GIS Bucket
Result: APPROVED
Remarks:
Notes: 76 MARKS RD CAMERON 28326.

Inspection Type: MH FOUND/MARRIAGE WALL
Scheduled Date/Time: 11/27/2024
Completed Date/Time: 11/27/2024
Inspector: Ricardo D Honrada
Result: DISAPPROVED
Remarks: eTRAKiT Inspection Request
Notes: 11/26/2024 11:55 AM RAVEN ROCK MOBILE HOME MOVER

Contact Name: RAVEN ROCK MOBILE HOME MOVER
Site Address: 76 MARKS RD
Phone: 9197753600
e-Mail: crubio201@gmail.com

Marriage connection ok. Wire cable left side needs to secure. Insulate the water pipe. Needs PRV, TXV. Some flexible duct needs 4 inches above ground. Water heater electrical connections need lock nuts. Some electrical boxes wires exposed. Sewer pipes leak test ok.





Harnett County
420 McKinney Pkwy

LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: MH FOUND/MARRIAGE WALL
Scheduled Date/Time: 12/4/2024
Completed Date/Time: 12/4/2024
Inspector: Ricardo D Honrada
Result: DISAPPROVED
Remarks: eTRAKiT Inspection Request
Notes: 12/3/2024 9:29 AM RAVEN ROCK MOBILE HOME MOVER

Contact Name: RAVEN ROCK MOBILE HOME MOVER
Site Address: 76 MARKS RD
Phone: 9197753600
e-Mail: crubio201@gmail.com

Insulate the water pipes under the mobile home where exposed. Condensation of air handler needs to be outside. Need drainage pipes from pressure relief valve of water heater, need go outside.

Inspection Type: MH FOUND/MARRIAGE WALL
Scheduled Date/Time: 12/9/2024
Completed Date/Time: 12/9/2024
Inspector: Ricardo D Honrada
Result: APPROVED W/EXC
Remarks: eTRAKiT Inspection Request
Notes: 12/5/2024 9:56 AM RAVEN ROCK MOBILE HOME MOVER

Contact Name: RAVEN ROCK MOBILE HOME MOVER
Site Address: 76 MARKS RD
Phone: 9197753600
e-Mail: crubio201@gmail.com

Need ground rods will check in final.



Harnett County
420 McKinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

Inspection Type: FOUNDATION SURVEY
Scheduled Date/Time: 12/12/2024
Completed Date/Time:
Inspector: CP Bucket
Result:
Remarks: eTRAKiT Inspection Request
Notes: 12/11/2024 2:44 PM RAVEN ROCK MOBILE HOME MOVER

Contact Name: RAVEN ROCK MOBILE HOME MOVER

Site Address: 76 MARKS RD

Phone: 9197753600

e-Mail: crubio201@gmail.com