






CONTRACTOR: Lawrence Curtis
 919-708-2316



Both Roof Framing:
 2x8 Beams
 4x6 Post
 2x6 Rafter
 1/2 OSB
 Shingles



Job location: 320 Lucky Ln Bunn level NC
 Homeowner: Thad Strickland (910) 944-9404