Initial Application Date: 6-25-24	Application #
COUNTY OF HARNETT DEMOLITION Central Permitting 108 E. Front Street, Lillington, NC 27546 Phone: (910) 893-75	
LANDOWNER: Hoffman Carolina, LLC Mailing Address:	5826 Solitude Way
City: Duhan State: NC Zip 27713 Contact # 919.)	73-4299 Email: Din Otherscarp con
APPLICANT*: Ceal Holcomb Renovations Inc Mailing Address:	
City: Ralcig State: NC Zip: 27015 Contact # 919 - 8 *Please fill out applicant information if different than landowner	372-4040 Email: Charmolition a Moh Con
CONTACT NAME APPLYING IN OFFICE:	Phone #
PROPERTY LOCATION: Subdivision: 9448 US 40	Lot #:Lot Size:
State Road #State Road Name:	Map Book&Page: /
Parcel:PIN:	
Zoning: Flood Zone: Watershed: Deed Book&Page:	1
SPECIFIC DIRECTIONS TO THE PROPERTY FROM LILLINGTON:	
Structure(s) to be demolished & removed: Single family dwelling Ma	anufactured HomeOther (specify)
Structures (existing and/or proposed): Single family dwellings Manu	
Water Supply: () County (V_) Existing Well	
Sewage Supply: (<u>V</u>) Existing Septic Tank () County Sewer	
* If a new structure is to be replaced on this lot, please ensure that existing	g septic system is not damaged.
* If an existing well is on site and is to be discontinued, please contact Har	nett County Environmental Health for assistance.
*Upon the issuance of the Certificate of Compliance, the Harnett County T	ax Department shall be notified of the removal to
ensure proper listing.	
*The demolition contractor is responsible for submitting verification of prop	per disposal prior to the Final inspection.
PLEASE NOTEFailure to completely demolish, remove, and clear the	
of Compliance. Thus, future permits for the property will be denied, and file	nes may be imposed for failure to complete demolition/
removal.	
If permits are granted I agree to conform to all ordinances and laws of the State of North Car	roling regulating such work and the appairing of the second
I hereby state that foregoing statements are accurate and correct to the best of my knowledge	
(1) 2/1/1	
Coop (V) (Co.)	4-25-24 Date
- January	- 4.0

This application expires 6 months from the initial date if no permits have been issued

		or changes to Commercial (not residential description of the control of the characters of the characte
nolish any building including residences de consibility to properly notify the Departm	emolished for commercial or in ent of Health and Human S	tos Inspector must be provided with application industrial expansion or structures. It is the contractervices Division of Public Health – Health Hazagin whether or not the building is known to contracted.
I hereby certify that the information or	this application is correct a	and that all work in connection with the above
		n work complies with the requirements of the N
State Building Codes and applicable	Harnett County Ordinances	. Call for inspection at proper stage of work.
Teil Holand	6-25-24	27551
CONTRACTOR / APPLICANT	DATE	LICENSE NO. (If applicable)
and a series the Demonstrative of the Market		
		r requirements and permit information.
		r requirements and permit information.
ease contact the Department of Health a p://www.epi.state.nc.us/epi/asbestos/ah		r requirements and permit information.

From: michael@thecscgrp.com @

Subject: Demo

Date: June 25, 2024 at 10:02 AM


To: Cecil Holcomb chdemolition@aol.com



Cecil, Please proceed with the demolition of 9648 US 401N Fuquay Varina 27526 per the attached plan.

Thanks

Michael Snoberger The CSC Group VP Land Development 925-683-0415





June 24, 2024

Mr. Cecil Holcomb - Cecil Holcomb Demolition

8315 La Matisse Road, Raleigh NC 27615

Subject:

Asbestos Containing Building Material Survey

9648 US 401 Fuquay-Varina, NC

Dear Mr. Holcomb:

Bar-Lyn Enterprises, Inc, was contracted to conduct Asbestos Containing Building Material Survey for the reference site. The survey for 9648 US 401 Fuquay-Varina, NC was conducted on June 18, 2024.

Bar-Lyn Enterprises, Inc understands that the subject is scheduled for selective renovation or demolition. In order to facilitate the renovation or demolition, Bar-Lyn Enterprises, Inc performed a survey to identify asbestos containing materials which are required to be removed prior to renovation or any demolition activities.

The survey was performed by Bar-Lyn Enterprises, Inc inspector Peter Mitchell (NC Accredited Inspector #13224). The survey began with a visual inspection of accessible areas for the presence of suspect asbestos containing materials. Both friable and nonfriable suspect asbestos containing material were considered during the course of the survey.

Bar-Lyn Enterprises, Inc. collected Thirty-Five (35) Suspect Asbestos Bulk Samples. The samples were submitted Carolina Environmental, Inc. for analyses using polarized light microscopy. A tabular summary of the analytical results is provided in attachment. The US Environmental Protection Agency (EPA) classifies material containing more than 1% asbestos as ACM. The materials found to contain regulated levels of ACM are listed below:

After reviewing data from the samples taken, the following materials were found to contain asbestos for House #1. None of the materials were found to contain asbestos for the Collapsed Barn #1, House #2, or Tobacco Barn #3.

House #1

Material	General Location	Type and Percentage of Asbestos Present		Approximate Amount	
2A,2B	Throughout – Exterior Siding	Transite Siding 15	5%	1,500 Sq. Ft.	NF
3A,3B,3C	Throughout	Glazing 2	2%	13 Windows	NF
4A,4B	Kitchen, Closet, Hall, & Bath	Sheetgood 20 Mastic 2	1% 2%	240 Sq. Ft.	NF
5A,5B	Mid Rt. BR	Sheetgood 20 Mastic 2	1% 2%	210 Sq. Ft.	NF
7A,7B,7C	Throughout	DW/JC <1	%	4,350 Sq. Ft.	F

RECOMMENDATIONS

Drywall and Joint Compound has less than 1% Chrysotile. Current EPA regulations do not regulate the removal of building materials with trace amounts (<1%) of asbestos. However, OSHA regards materials with any amount of asbestos to be a potential exposure hazard if the material is disturbed. Therefore, work practices specified in the OSHA Standard (CFR 29 1962.1101) must be followed if the materials are disturbed, removed or demolished. Proper training and personal protection measures are also required as specified in the OSHA Standards.

The National Emissions Standard for Hazardous Air Pollutants (NESHAP) requires the removal of asbestos-containing materials prior to renovation or demolition activities. Matrix recommends asbestos removal be performed by a qualified asbestos abatement contractor, using North Carolina accredited personnel, in accordance with applicable federal and state regulations governing the removal of asbestos-containing materials.

Collapsed Barn #1

Material	General Location	Type and Percentage of Asbestos Present	Approximate Amount
None			

Tobacco Barn #3

Material	General Location	Type and Percentage of Asbestos Present	Approximate Amount
None			

^{*}Note: There was no suspected asbestos containing materials identified for Tobacco Barn #1, Tobacco Barn #2, (6) Six Metal Storage Buildings, Collapsed Barn #2, and Collapsed Shelter.

Continue:

F=Friable NF=Non Friable

Any demolition/renovation work in which ACM is disturbed must be in compliance with EPA, OSHA and the State of North Carolina regulations. Please note that the asbestos abatement contractor must notify the North Carolina Department of Health and Human Services (HHS) ten (10) days prior to the disturbance of ACM if it is friable or becomes friable and greater than or equal to 160 square feet, 260 linear feet or 35 cubic feet.

Please contact our office should you have any additional questions.

Respectfully,
BAR-LYN ENTERPRISES, INC.

Peter D. Mitchell
Peter D. Mitchell**
NC Accredited Inspector #13224

Photos of House #1, Collapsed Barn#1, Collapsed Barn #2, House #2, Tobacco Barn #1, #2, #3, Metal Storage Buildings, & Collapsed Shelter Inspected:

9648 US 401 Fuquay-Varina, NC

House #1




Collapsed Barn #2



Collapsed Barn #1



House #2



Continue:

Tobacco Barn #1



Tobacco Barn #2



Tobacco Barn #3



Collapsed Shelter





Metal Storage Buildings (6)





Additional Information & Photos







Continue:





*Attachments: Chain of Custody & Laboratory Report