

Sheet:
Property ID:
Lot #:
File #:
Code:

Owner: SRP Cameron Applicant:

Owner: 71 Applicant: Red Brown Rd Date Evaluated: 360 GPD Property Size: 360 GPD
Address: 423 Design Flow (.1949): 360 GPD
Proposed Facility: DWMH Property Recorded:
Location of Site:
Water Supply: ☒ Public ☐ Individual ☐ Well ☐ Spring
Evaluation Method: ☒ Auger Boring ☐ Pit ☐ Cut
Type of Wastewater: ☒ Sewage ☐ Industrial Process ☐ Mixed

[illegible]

Description	Initial System	Repair System
Available Space (.1945)	✓	✓
System Type(s)	✓	✓
Site LTAR	.6	.6

Other Factors (.1946):
Site Classification (.1948):
Evaluated By: *REHS*
Others Present:

LANDSCAPE POSITIONS	GROUP	TEXTURES	1955 L.TAR	CONSISTENCE MOIST	WBI
R-RIDGE	I	S-SAND	1.2-0.8	VFR-VERY FRILABLE	NS-NON-STICKY
S-SHOULDER SLOPE		LS-LOAMY SAND		FR-FRILABLE	SS-SLIGHTLY STICKY
L-LINEAR SLOPE				FI-FIRM	S-STICKY
FS-FOOT SLOPE	II	SL-SANDY LOAM	0.8-0.6	VFI-VERY FIRM	VS-VERY STICKY
N-NOSE SLOPE		L-LOAM		EFI-EXTREMELY FIRM	NP-NON-PLASTIC
H-HEAD SLOPE	III	SI-SILT	0.6-0.3		SP-SLIGHTLY STICKY
CC-CONCLAVE SLOPE					P-PLASTIC
CV-CONVEX SLOPE		SH-SILT LOAM			VP-VERY PLASTIC
T-TERRACE		CL-CLAY LOAM			
FP-FLOOD PLAN	IV	SCL-SANDY CLAY LOAM	0.4-0.1		
		SC-SANDY CLAY			
		C-CLAY			
		MINERALOGY			
		SLIGHTLY EXPANSIVE			
		EXPANSIVE			
STRUCTURE					
SG-SINGLE GRAIN					
M-MASSIVE					
CR-CRUMB					
GR-GRANULAR					
SBK-SUBANGULAR BLOCKY					
ABK-ANGULAR BLOCKY					
PL-PLATY					
FR-FRISMATIC					

Show profile locations and other site features (dimensions, references or benchmark, and North)

