Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION						
for ON-SITE	WASTEWATER SYSTEM					

. A.
GPD Property Size:
☐ Spring ☐ Other
☐ Cut
ss Mixed

P R O F I L E	.1940 Landscape Position/ Slope %	Horizon Depth (ln.)	SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
			.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LT	
1	1	0-12	LS		104R6/1	748"	,	_	5.	3
	2.78	12-48	Sci		> 10"					
2	L	0-12	LS		10426/1	>48"		_	5.	3
	2-7%	12-48	SCI		10426/1 > C10"					
3	L	0-20	LS		>48"	>48	_		5.	3
	L 2-7%	20-48	SCI			_ = = = = = =				

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)	-		Site Classification (.1948): Evaluated By: Evaluated By:
System Type(s)			Others Present:
Site LTAR	.3	-3	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	III	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC
	IV	SIC-SILTY CLAY C-CLAY SC-SANDY CLAY	0.4 - 0.1		
STRUCTURE SG-SINGLE GRAIN		MINERALOGY SLIGHTLY EXPANSIVE			
M- MASSIVE CR-CRUMB GR-GRANULAR		EXPANSIVE			
SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY PR-PRISMATIC			s		
	Show profi	le locations and other site feature	es (dimensions, refe	erences or benchmark, and North)	
					. —
		1 1 6	XDWM	\wedge	
	+		200.		

PASTUR

3

(2)

(1)

Fence