

MAPLES SEPTIC TANK SERVICE, INC.

80 Thomas Kelly Road

Sanford, NC 27330

(919) 258-3750 Phone (919) 258-3914 Fax

Inspection Certification #24751

No representation, warranties, or opinions are hereby given, written or expressed otherwise, as to the future performance of onsite wastewater system described herein. This onsite wastewater system inspection is a presentation of system facts on date of inspection.

Address of Property 658 Love Grove Church Rd

Current Owner on Record _____

Inspection Requested by Gisela Perez

Other Name _____

Company/Contact Number 919-353-5007

Date of Inspection 3/14/25

Copy of Operations permit from _____ County of Environmental Health attached.

_____ Operations Permit not available.

Type of water supply ☒ Well _____ Public Water _____ Community Water

Location of Septic Tank and Septic Tank details:

20 ft from house or structure

75 ft from well if applicable

_____ ft from water line if applicable

50 ft from property line

6" Approximate distance from surface to top of tank

_____ Access riser(s) _____ yes _____ no describe: _____

_____ Tank lids intact ☒ yes _____ no

_____ Tank has baffle wall

☒ Inflow to tank is noted as sufficient

_____ Inflow to tank is noted as insufficient or blocked

_____ Outlet has a filter _____ yes _____ no _____ unknown

_____ Outlet T is present ☒ yes _____ no

_____ Effluent leaves the outlet _____ yes ☒ no _____ unknown

_____ Roots present in tank ☒ yes _____ no _____ unknown

Evidence of infiltration into tank of surface water yes no

Evidence of tank leakage noted

Unable to locate tank. System inspection cannot be completed until tank is located

Garbage Disposal yes no ? unknown

Number of bedrooms 3

Date tank was last pumped 3/14/25

Percentage of sludge detected in tank 0 %

Does System have a pump tank? yes (complete blanks below) no

ft from house or structure

ft from well if applicable

ft from water line if applicable

ft from property line

Approximate distance from surface to top of tank

Access riser(s) in place yes no

ft from Septic tank

Location of control Panel

Electrical connection are in place and properly grounded

Alarm is working properly

Pump is working properly

Dosing volume correct

Unable to operate pump/alarm due to lack of electricity at site at time of inspection

System requires a subsurface operator yes no

If yes, Operator Name Contact Number

Copy of most recent operator report attached yes no

Drain field located:

10 ft from property line

5 ft from septic/pump tank

1 # of lines located

100+ ft length of system

Type of system: Conventional Innovative Experimental Controlled Demo
Pretreatment: Type of Pretreatment

Brief Description of System Type: Gravel

 Evidence of past or current surfacing at time of inspection


☒ Large trees or other vegetation noted over drain field area, if YES briefly describe Drain
lines are in the woods

 Evidence of traffic over drain field, if YES briefly describe

Other pertinent facts noted during inspection Tank is an older
style, but in good condition. There is
a concrete T in the tank. Lines
were water tested, and they are
not taking water.

Inspector Name: Maples Septic Tank Services, INC. Owner Terry R. Maples Certification #24751

80 Thomas Kelly Road, Sanford NC 27330 Office phone (919) 258-3750 Cell (919) 356-5785

Inspectors Signature:  Date: 3/14/25