Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Location of Site: Water Supply: Evaluation Method: ☑ Auger Boring	Property Recorded: c Individual Well Pit Cut	☐ Spring	Other
Type of Wastewater: Sewa		☐ Mixed	

O F I L E	.1940 Landscape Position/ Slope %		SOIL MORPHOLOGY .1941		OTHER PROFILE FACTORS					
		Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color		.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	L	0-26	45	Fr/uspx	>4	8"	>48"	_	_	5.4
	7-52	26-48	SCI	Fi/sipx	-					
2	L	0-24	25	Fr/NSPX	>48	"	>48"		_	5.4
	2.5%	24-48	SCI	Filsigx		i i				
			i	1						
3,4	4	0-18	45	Fr/NSPX	>48		>48"	_		5-4
	2-5%	18-48	Ser							
					17					
								1		
								1		
							*	\$		
					* i					
						1 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
						1 .		9	3	
			·	1	4	- 12				

Description	Initial System	Repair System	Other Factors (.1946): Site Classification (.1948):
Available Space (.1945)	4		Evaluated By:
System Type(s)	L		Others Present:
Site LTAR	.4	.4	

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE FS-FOOT SLOPE	I	S-SAND LS-LOAMY SAND	0.8 - 0.6	VFR-VERY FRIABLE FR-FRIABLE FI-FIRM	NS-NON-STICKY SS-SLIGHTY STICKY S-STICKY
N-NOSE SLOPE H-HEAD SLOPE		L-LOAM	0.0 - 0.0	VFI-VERY FIRM EFI-EXTREMELY FIRM	VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC

0.4 - 0.1

STRUCTURE
SG-SINGLE GRAIN
M- MASSIVE
CR-CRUMB
GR-GRANULAR
SBK-SUBANGULAR BLOCKY
ABK-ANGULAR BLOCKY
PL-PLATY

MINERALOGY SLIGHTLY EXPANSIVE

SIC-SILTY CLAY

EXPANSIVE

C-CLAY SC-SANDY CLAY

ΙV

