



Harnett County
420 McKinney Pkwy
LILLINGTON, NC 27546
Phone:
Fax:

10/23/2025

SUBJECT: **BRES2508-0044**
BUILDING RESIDENTIAL

To: E.J.S. Homes Inc.

Here are the results of all Inspections located at **959 MCFARLAND RD:**

Inspection Type: FINAL**
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: FOOTING
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: FOUNDATION
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: MONO SLAB
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:



Harnett County
420 McKinney Pkwy
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: OPEN FLOOR
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: SLAB
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: UNDER SLAB TRADES
Scheduled Date/Time:
Completed Date/Time:
Inspector: Steven Gazlay
Result:
Remarks:
Notes:

Inspection Type: ROUGH IN
Scheduled Date/Time: 9/25/2025
Completed Date/Time: 9/25/2025
Inspector: John B Kokoszka
Result: DISAPPROVED
Remarks:
Notes: House was locked at the time of inspection

Inspection Type: ROUGH IN
Scheduled Date/Time: 9/29/2025
Completed Date/Time: 9/29/2025
Inspector: John B Kokoszka
Result: DISAPPROVED
Remarks:
Notes: Left bathroom Chase missing insulation air bar fire stop need to seal hole at floor need to fire block the topLooks like some of the floor system has been fixed needs to be the codeNo treated wood in contact with Masonary
Left bathroom Chase missing insulation air bar fire stop need to seal hole at floor need to fire block the topLooks like some of the floor system has been fixed needs to be the codeNo treated wood in contact with Masonary



Harnett County
420 McKinney Pkwy
LILLINGTON, NC 27546
Phone:
Fax:

Inspection Type: ROUGH IN
Scheduled Date/Time: 10/7/2025
Completed Date/Time: 10/7/2025
Inspector: John B Kokoszka
Result: DISAPPROVED
Remarks: eTRAKiT Inspection Request
Notes: 10/3/2025 11:06 AM E.J.S. Homes Inc.

Contact Name: E.J.S. Homes Inc.
Site Address: 959 MCFARLAND RD
Phone: 9104838373
e-Mail: admin@ejshomesinc.com

10/3/2025 11:11 AM E.J.S. Homes Inc.

Contact Name: E.J.S. Homes Inc.
Site Address: 959 MCFARLAND RD
Phone: 9104838373
e-Mail: admin@ejshomesinc.com

Customer said the back door will be unlocked.
Missing insulation and air barrier behind left tubMissing insulation baffles

Inspection Type: INSULATION
Scheduled Date/Time: 10/15/2025
Completed Date/Time: 10/15/2025
Inspector: John B Kokoszka
Result: DISAPPROVED
Remarks: eTRAKiT Inspection Request
Notes: 10/13/2025 8:56 AM E.J.S. Homes Inc.

Contact Name: E.J.S. Homes Inc.
Site Address: 959 MCFARLAND RD
Phone: 9104838373
e-Mail: admin@ejshomesinc.com

Need to foam around windows and doors per codeMissing insulation exterior wall in living roomNeed to remove all exterior wall need toR15 some areas aren't r15



Harnett County
420 McKinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

Inspection Type: ROUGH IN
Scheduled Date/Time: 10/15/2025
Completed Date/Time: 10/15/2025
Inspector: John B Kokoszka
Result: APPROVED
Remarks: eTRAKiT Inspection Request
Notes: 10/13/2025 8:55 AM E.J.S. Homes Inc.

Contact Name: E.J.S. Homes Inc.
Site Address: 959 MCFARLAND RD
Phone: 9104838373
e-Mail: admin@ejshomesinc.com

Inspection Type: INSULATION
Scheduled Date/Time: 10/16/2025
Completed Date/Time: 10/16/2025
Inspector: John B Kokoszka
Result: APPROVED
Remarks: eTRAKiT Inspection Request
Notes: Back door unlocked