Department of Environment, Health and Natural Resources Division of Environmental Health On-Site Wastewater Section

Sheet: Property ID: Lot #: File #: Code:

SOIL/SITE EVALUATION

Other

P R O F I	.1940		SOIL MORPHOLOGY OTHER .1941 PROFILE FACTORS						
L E #},~	Landscape Position/ Slope %	Horizon Depth (In.)	.1941 Structure/ Texture	.1941 Consistence Mineralogy	.1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	L	0.31	U	f-/NIPX	104R6/2 = 38"	>48"	_	_	5.5
	2-52	31-48	D ICI	Folsopx Folsopx	<i>≥38''</i>				
2	L 2-5%	0-24	LS	f-/uspx	104R 6/2	>(8'	_		5.5
	2-52	24-48	SCI	Filsspx	104R 6/2 = 73"				
				,	e				
							.1		
								*** * ** 1	
					4			1 1 12 12	4

Description	Initial System	Repair System
Available Space (.1945)	-	L
System Type(s)	-	~
Site LTAR	- 5	. 5

Other Factors (.1946): Site Classification (.1948): Evaluated By:

Others Present:

COMMENTS: ____

LANDSCAPE POSITIONS	GROUP	TEXTURES	. <u>1955 LTAR</u>	CONSISTENCE MOIST	WET
R-RIDGE S-SHOULDER SLOPE L-LINEAR SLOPE	I	S-SAND LS-LOAMY SAND	1.2 - 0.8	VFR-VERY FRIABLE FR-FRIABLE	NS-NON-STICKY SS-SLIGHTY STICKY
FS-FOOT SLOPE N-NOSE SLOPE H-HEAD SLOPE	II	SL-SANDY LOAM L-LOAM	0.8 - 0.6	FI-FIRM VFI-VERY FIRM EFI-EXTREMELY FIRM	S-STICKY VS-VERY STICKY NP-NON-PLASTIC
CC-CONCLAVE SLOPE CV-CONVEX SLOPE T-TERRACE FP-FLOOD PLAN	Ш	SI-SILT SIL-SILT LOAM CL-CLAY LOAM SCL-SANDY CLAY LOAM	0.6 - 0.3		SP-SLIGHTLY STICKY P-PLASTIC VP-VERY PLASTIC
	IV	SIC-SILTY CLAY C-CLAY SC-SANDY CLAY	0.4 - 0.1		
STRUCTURE SG-SINGLE GRAIN M- MASSIVE		MINERALOGY SLIGHTLY EXPANSIVE			
CR-CRUMB GR-GRANULAR SBK-SUBANGULAR BLOCKY ABK-ANGULAR BLOCKY PL-PLATY	١	EXPANSIVE			

