


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER

FACTORS		PROFILES												
		1	2	3	4	5	6	7	8	9	10			
LANDSCAPE POSITION	.1940													
SLOPE (%)	.1940													
HORIZON 1 DEPTH		0-2"	0-3"	0-2"										
TEXTURE GROUP	.1941(A)(1)	FILL	FILL	FILL										
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 2 DEPTH		2'-38"	3"X	2"X										
TEXTURE GROUP	.1941(A)(1)	SIC	SIC	SIC										
CONSISTENCE	.1941	FR	FR	FR										
STRUCTURE	.1941(A)(2)	SBK	SBK	SBK										
MINERALOGY	.1941(A)(3)	S/P	S/P	S/P										
HORIZON 3 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
HORIZON 4 DEPTH														
TEXTURE GROUP	.1941(A)(1)													
CONSISTENCE	.1941													
STRUCTURE	.1941(A)(2)													
MINERALOGY	.1941(A)(3)													
SOIL WETNESS	.1942	0.7"	0.7"	0.7"										
RESTRICTIVE HORIZON	.1944													
SAPROLITE	.1943, 1956													
CLASSIFICATION	.1948	PS	PS	PS										
LONG TERM ACCEPTANCE RANGE	.1955	.4	.4	.4										

FINAL EVALUATION BASED ON PITS USE MAP



PREPARED IN THE OFFICE OF:



Kimley-Horn