

HTE# 16-5-39496

HARNETT COUNTY HEALTH DEPARTMENT  
ENVIRONMENTAL HEALTH  
307 CORNELIUS HARNETT BOULEVARD  
LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

NAME: SHANE McLeod PHONE # 910-591-9727

ADDRESS 121 Brandon Dr Lillington N.C. 27546

NAME OF MOBILE HOME PARK OR S/D \_\_\_\_\_

NAME OF OWNER (IF DIFFERENT) Erwin Chapel Church

ADDRESS OF OWNER (IF DIFFERENT) 133 Erwin Chapel Rd

PROPERTY LOCATION: STATE ROAD NAME AND # SR 2011 Erwin Chapel

**PURPOSE OF INSPECTION:** Addition to Fellowship Hall

The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If this system should malfunction, the owner is responsible for any necessary repairs.

**THIS INSPECTION IS VOID IF:**

- (1) the intended use of the septic system should change, and/or
- (2) the system should fail or malfunction, and/or
- (3) the owner or tenant of the property changes, and/or
- (4) after six months

**BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM  
DO NOT DRIVE OR PARK ON SEPTIC SYSTEM**

**AUTHORIZATION OF EXISTING SYSTEM**

James E. Markham  
Signature of Environmental Health Specialist

11-8-16  
Date