SITE/SOIL EVALUATION

APPLICANT NAME _____ DATE _____

FACTORS		PROF									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940										
SLOPE (%)	.1940										
HORIZON 1 DEPTH		0-10	0-7	0-16							
Texture Group	.1941(A)(1)	LS	SL	LS							
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 2 DEPTH		10-20	7-24	28							
Texture Group	.1941(A)(1)	SCL	SCL	SCL							
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 3 DEPTH		20-~~54~~	24-~~54~~	60							
Texture Group	.1941(A)(1)	LS	LS	SL							
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942	>54	>54	>60							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948										
LONG TERM ACCEPTANCE RATE	.1955	.8	.8	.8							