


SITE/SOIL EVALUATION FOR ON-SITE WASTEWATER


APPLICANT NAME _____

DA _____

FACTORS		PROFILES									
		1	2	3	4	5	6	7	8	9	10
LANDSCAPE POSITION	.1940	L	L	L							
SLOPE (%)	.1940	2	2	2							
HORIZON 1 DEPTH		0-36									
Texture Group	.1941(A)(1)	SL									
Consistence	.1941	FL									
Structure	.1941(A)(2)	GR									
Mineralogy	.1941(A)(3)	NONP	II	II							
HORIZON 2 DEPTH		36-48									
Texture Group	.1941(A)(1)	SCL									
Consistence	.1941	FL									
Structure	.1941(A)(2)	GR									
Mineralogy	.1941(A)(3)	NSSP									
HORIZON 3 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
HORIZON 4 DEPTH											
Texture Group	.1941(A)(1)										
Consistence	.1941										
Structure	.1941(A)(2)										
Mineralogy	.1941(A)(3)										
SOIL WETNESS	.1942	36	36	36							
RESTRICTIVE HORIZON	.1944										
SAPROLITE	.1943/.1956										
CLASSIFICATION	.1948										
LONG TERM											
ACCEPTANCE RATE	.1955	.5	.5	.5							



Wüstung Bayern cont.
add'l
0694-22-4544
RA-30



WIFE BOBBY H. BROADWELL
DB 1807.683
POWER 082.

PC # F-3157
64102

VICINITY MAP
 NTS

