

HTE # 06-50014734

HAMILTON COUNTY HEALTH DEPARTMENT  
ENVIRONMENTAL HEALTH SECTION

18484

# OPERATIONS PERMIT

Name: (owner) Richard Quinonez  New Installation  Septic Tank  Repair

Property Location: SR# 1101 Needmore  Nitrification Line  Expansion

Subdivision WF Hamm Ent Lot # 2 Tax ID # \_\_\_\_\_ Quadrant # \_\_\_\_\_

Contractor: Mike Simpson Registration # \_\_\_\_\_

Basement with Plumbing:  Garage:

Water Supply:  Well  Public  Community

Distance From Well: 50 ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system:  Conventional  Other Tree Chips

Size of tank: Septic Tank: 1000 gallons Pump Tank: \_\_\_\_\_ gallons

Subsurface Drainage Field No. of ditches 1 exact length of each ditch 160 ft. width of ditches 3 ft. depth of ditches 18 1/4 in.

French Drain Required: \_\_\_\_\_ Linear feet

Date: 07-20-06

PERMIT NO. 23054

Inspected by: J. W. A. S.

BTS-1000  
11B-107  
3-15-06

