

PREPARED 12/18/08, 8:17:18
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 1
DATE 12/17/08

ADDRESS : 379 DOLL HOUSE RD
CONTRACTOR : MCNEILL SAMMY E
OWNER : SWANN PEARLIE
PARCEL : 03-9579- - -0112- - -
APPL NUMBER: 08-50021317 CP ADD & ALTER RESIDENTIAL

SUBDIV:
PHONE : (919) 258-3137
PHONE :

DIRECTIONS : TAKE 24/27 TO BARBEQUE CHURCH ROAD,
TAKE RIGHT. GO APPROX 5 MILES, TAKE A
RIGHT ON DOLL HOUSE ROAD. GO APPROX 1.5
MILES, HOUSE IS ON THE RIGHT.
T/S: 11/26/2008 03:02 PM RDCONTE ---

STRUCTURE: 000 000 12X32 ADD/ALTER

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

SEPTIC - EXISTING? : EXISTING

WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

	REQUESTED	INSP	DESCRIPTION
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS
B103 01	12/17/08	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001717461
	12/17/08	CA	need footing inspection
B101 01	12/17/08	TI	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001719053

COMMENTS AND NOTES

FS

PREPARED 12/19/08, 14:08:45
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 42
DATE 12/22/08

ADDRESS : 379 DOLL HOUSE RD
CONTRACTOR : MCNEILL SAMMY E
OWNER : SWANN PEARLIE
PARCEL : 03-9579- - -0112- - -
APPL NUMBER: 08-50021317 CP ADD & ALTER RESIDENTIAL
DIRECTIONS : TAKE 24/27 TO BARBEQUE CHURCH ROAD,
TAKE RIGHT. GO APPROX 5 MILES, TAKE A
RIGHT ON DOLL HOUSE ROAD. GO APPROX 1.5
MILES, HOUSE IS ON THE RIGHT.
T/S: 11/26/2008 03:02 PM RDCONTE ---

STRUCTURE: 000 000 12X32 ADD/ALTER

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

SEPTIC - EXISTING? : EXISTING

WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B103 01	12/17/08	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001717461
	12/17/08	CA	need footing inspection
B101 01	12/17/08	FS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001719053
	12/17/08	AP	
B103 02	12/22/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001719812

COMMENTS AND NOTES

ADDRESS . : 379 DOLL HOUSE RD
CONTRACTOR : MCNEILL SAMMY E
OWNER . : SWANN PEARLIE
PARCEL . : 03-9579- - -0112- - -
APPL NUMBER: 08-50021317 CP ADD & ALTER RESIDENTIAL
DIRECTIONS : TAKE 24/27 TO BARBEQUE CHURCH ROAD,
TAKE RIGHT. GO APPROX 5 MILES, TAKE A
RIGHT ON DOLL HOUSE ROAD. GO APPROX 1.5
MILES, HOUSE IS ON THE RIGHT.
T/S: 11/26/2008 03:02 PM RDCONTE ---

STRUCTURE: 000 000 12X32 ADD/ALTER

FLOOD ZONE . . . : FLOOD ZONE X
BEDROOMS . . . : 4.00 SEPTIC - EXISTING? . . . : EXISTING
WATER SUPPLY . . . : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B103 01	12/17/08	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001717461
	12/17/08	CA	need footing inspection
B101 01	12/17/08	FS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001719053
	12/17/08	AP	
B103 02	12/22/08	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001719812
	12/22/08	AP	
B105 01	12/29/08	TI	R*OPEN FLOOR VRU #: 001720917

----- COMMENTS AND NOTES -----

T
B3

PREPARED 1/23/09, 14:00:11
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 13
DATE 1/26/09

ADDRESS : 379 DOLL HOUSE RD SUBDIV:
CONTRACTOR : MCNEILL SAMMY E PHONE : (919) 258-3137
OWNER : SWANN PEARLIE PHONE :
PARCEL : 03-9579- - -0112- - -
APPL NUMBER: 08-50021317 CP ADD & ALTER RESIDENTIAL
DIRECTIONS : TAKE 24/27 TO BARBEQUE CHURCH ROAD,
TAKE RIGHT. GO APPROX 5 MILES, TAKE A
RIGHT ON DOLL HOUSE ROAD. GO APPROX 1.5
MILES, HOUSE IS ON THE RIGHT.
T/S: 11/26/2008 03:02 PM RDCONTE ---

STRUCTURE: 000 000 12X32 ADD/ALTER

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

SEPTIC - EXISTING? : EXISTING

WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B103 01	12/17/08	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001717461
	12/17/08	CA	need footing inspection
B101 01	12/17/08	FS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001719053
	12/17/08	AP	
B103 02	12/22/08	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001719812
	12/22/08	AP	
H824 01	12/23/08	JW	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001721497
	12/23/08	AP	
B105 01	12/29/08	FS	R*OPEN FLOOR VRU #: 001720917
	12/29/08	AP	
R425 01	1/26/09	TI	FOUR TRADE ROUGH IN VRU #: 001728134

1-26-09 DA-MR

----- COMMENTS AND NOTES -----

HARNETT COUNTY

Building Inspections Dept.

108 E. Front St.

Lillington, NC 27546

910-893-7525

DO NOT REMOVE

DATE: 1-26-09

PERMIT# 08-50021317

ADDRESS: 379 doll House rd.

VIOLATIONS:

1. No floor vents installed
2. No dryer outlet installed
3. Wall between new and old must be fireblocked at ceiling line
4. Old wiring is ungrounded and I don't see where you are going to connect old to new wiring
5. Nail all holes in hanger joists under porch
6. Laundry / bathroom is not according to plans and the change has left some rafters un-supported and the load is not transmitted to the foundation girder
7. Siding was put on before inspection , I can't see rafters or girders or connections on porch

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

PREPARED 1/27/09, 13:58:55
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 19
DATE 1/28/09

ADDRESS : 379 DOLL HOUSE RD
CONTRACTOR : MCNEILL SAMMY E
OWNER : SWANN PEARLIE
PARCEL : 03-9579- - -0112- - -
APPL NUMBER: 08-50021317 CP ADD & ALTER RESIDENTIAL
DIRECTIONS : TAKE 24/27 TO BARBEQUE CHURCH ROAD,
TAKE RIGHT. GO APPROX 5 MILES, TAKE A
RIGHT ON DOLL HOUSE ROAD. GO APPROX 1.5
MILES, HOUSE IS ON THE RIGHT.
T/S: 11/26/2008 03:02 PM RDCONTE ---

SUBDIV:
PHONE : (919) 258-3137
PHONE :

STRUCTURE: 000 000 12X32 ADD/ALTER

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

SEPTIC - EXISTING? : EXISTING

WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B103 01	12/17/08	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001717461
	12/17/08	CA	need footing inspection
B101 01	12/17/08	FS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001719053
	12/17/08	AP	
B103 02	12/22/08	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001719812
	12/22/08	AP	
H824 01	12/23/08	JW	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001721497
	12/23/08	AP	
B105 01	12/29/08	FS	R*OPEN FLOOR VRU #: 001720917
	12/29/08	AP	
R425 01	1/26/09	MR	FOUR TRADE ROUGH IN VRU #: 001728134
	1/26/09	DA	1. no floor vents installed 2. no dryer outlet installed 3. wall between new and old area must be fireblocked 4. where is the connection for old house wiring? 5. nail all holes in hangers under porch 6. rafters over laundry area are unsupported and the load is not on the foundation 7. siding is already on , I cant see the rafters or girder on porch
R425 02	1/28/09	TI	FOUR TRADE ROUGH IN VRU #: 001729366
	1-28-9	DA-MR	

COMMENTS AND NOTES

HARNETT COUNTY

Building Inspections Dept.

108 E. Front St.

Lillington, NC 27546

910-893-7525

DO NOT REMOVE

DATE: 1-28-09

PERMIT# 08-50021317

ADDRESS: 379 doll house rd..

VIOLATIONS:

1. Dryer line must be smooth pipe not flex as installed
2. I will check it on insulation inspection
3. Ok to insulate and side

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

ADDRESS : 379 DOLL HOUSE RD
CONTRACTOR : MCNEILL SAMMY E
OWNER : SWANN PEARLIE
PARCEL : 03-9579- - -0112- - -
APPL NUMBER: 08-50021317 CP ADD & ALTER RESIDENTIAL

SUBDIV:
PHONE : (919) 258-3137
PHONE :

DIRECTIONS : TAKE 24/27 TO BARBEQUE CHURCH ROAD,
TAKE RIGHT. GO APPROX 5 MILES, TAKE A
RIGHT ON DOLL HOUSE ROAD. GO APPROX 1.5
MILES, HOUSE IS ON THE RIGHT.
T/S: 11/26/2008 03:02 PM RDCONTE ---

STRUCTURE: 000 000 12X32 ADD/ALTER

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

SEPTIC - EXISTING? : EXISTING

WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B103 01	12/17/08	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001717461
	12/17/08	CA	need footing inspection
B101 01	12/17/08	FS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001719053
	12/17/08	AP	
B103 02	12/22/08	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001719812
	12/22/08	AP	
H824 01	12/23/08	JW	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001721497
	12/23/08	AP	
B105 01	12/29/08	FS	R*OPEN FLOOR VRU #: 001720917
	12/29/08	AP	
R425 01	1/26/09	MR	FOUR TRADE ROUGH IN VRU #: 001728134
	1/26/09	DA	1. no floor vents installed 2. no dryer outlet installed 3. wall between new and old area must be fireblocked 4. where is the connection for old house wiring? 5. nail all holes in hangers under porch 6. rafters over laundry area are unsupported and the load is not on the foundation 7. siding is already on , I cant see the rafters or girder on porch
R425 02	1/28/09	MR	FOUR TRADE ROUGH IN VRU #: 001729366
	1/28/09	DA	ok to side and insulate but, the dryer vent must be smooth metal pipe not the flex installed now. I will check it on insulation inspect.
I129 01	1/30/09	TL	R*INSULATION INSPECTION VRU #: 001730247
R425 03	1/30/09	TL	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001730373

COMMENTS AND NOTES

FS

PREPARED 4/06/09, 13:59:09
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 12
DATE 4/07/09

ADDRESS : 379 DOLL HOUSE RD
CONTRACTOR : MCNEILL SAMMY E
OWNER : SWANN PEARLIE
PARCEL : 03-9579- - -0112- - -
APPL NUMBER: 08-50021317 CP ADD & ALTER RESIDENTIAL
DIRECTIONS : TAKE 24/27 TO BARBEQUE CHURCH ROAD,
TAKE RIGHT. GO APPROX 5 MILES, TAKE A
RIGHT ON DOLL HOUSE ROAD. GO APPROX 1.5
MILES, HOUSE IS ON THE RIGHT.
T/S: 11/26/2008 03:02 PM RDCONTE ---

SUBDIV:
PHONE : (919) 258-3137
PHONE :

STRUCTURE: 000 000 12X32 ADD/ALTER

FLOOD ZONE : FLOOD ZONE X

BEDROOMS : 4.00

SEPTIC - EXISTING? : EXISTING

WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B103 01	12/17/08	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001717461
	12/17/08	CA	need footing inspection
B101 01	12/17/08	FS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001719053
	12/17/08	AP	
B103 02	12/22/08	FS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001719812
	12/22/08	AP	
H824 01	12/23/08	JW	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001721497
	12/23/08	AP	
B105 01	12/29/08	FS	R*OPEN FLOOR VRU #: 001720917
	12/29/08	AP	
R425 01	1/26/09	MR	FOUR TRADE ROUGH IN VRU #: 001728134
	1/26/09	DA	1. no floor vents installed 2. no dryer outlet installed 3. wall between new and old area must be fireblocked 4. where is the connection for old house wiring? 5. nail all holes in hangers under porch 6. rafters over laundry area are unsupported and the load is not on the foundation 7. siding is already on , I cant see the rafters or girder on porch
R425 02	1/28/09	MR	FOUR TRADE ROUGH IN VRU #: 001729366
	1/28/09	DA	ok to side and insulate but, the dryer vent must be smooth metal pipe not the flex installed now. I will check it on insulation inspect.
I129 01	1/30/09	FS	R*INSULATION INSPECTION VRU #: 001730247
	1/30/09	AP	
R425 03	1/30/09	FS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001730373
	1/30/09	AP	
R429 01	4/07/09	FS	FOUR TRADE FINAL VRU #: 001751811

COMMENTS AND NOTES

FS

**DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: AS 1710R1

Owner: YARLIT SWAN

911 Address: 879 Ave Huse

State: Zip Code:

Date: 4-8-7

Building Official

PERMIT NUMBERS

Building Permit No.: 8-5-21517

Electrical Permit No.: 8-5-21817

Insulation Permit No.: 85-21317

Plumbing Permit No.: 8-5-21217

Mech. Permit No.: 8521317

MFG. Home: _____