

PREPARED 4/16/12, 13:55:21 INSPECTION TICKET PAGE Harnett County INSPECTOR: IVR DATE 4/17/12

SUBDIV: CAPTAINS LANDING

PHONE :

PHONE :

ADDRESS . /: 37 NATCHEZ TRACE

CONTRACTOR :

OWNER . . . : MILLS KENNETH & DORIS

PARCEL . . . 05-0613- - -0244- -APPL NUMBER: 10-50023725 CP ADD & ALTER RESIDENTIAL

DIRECTIONS : T/S: 02/03/2010 05:49 PM RDCONTE ---NATCHEZ TRACE / CAPTAINS LANDING #3 TAKE 401N TO CHRISTAN LIGHT ROAD, T/L ON COKESBURY. T/L ON RIVER RD. T/R INTO CAPTAINS LANDING. T/L ON NATCHEZ TRACE. LOT IS ON THE LEFT ABOUT 200' FROM

TURN. IT IS A 2 STORY STORAGE BLDG FROM

LOWES.

PREMISE # WAITING ON CUS

-----STRUCTURE: 000 000 16X24 2STORY STORAGE TO BE RESIDENCE

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 1.00 SEPTIC - EXISTING? : NEW

WATER SUPPLY : EXT WELL

PERMIT: CPBP 00 CP BUILDING PERMIT					
	REQUESTED	INSP	DESCRIPTION		
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS		
H824 01	3/26/10	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001901883		
	3/26/10	AP	1/S: 03/29/2010 11:27 AM SSTEWART		
B101 01	8/02/10	KS	T/S: 03/29/2010 11:28 AM SSTEWART		
	8/02/10	DA	 Footing dug to slope of grade. Needs stepdowns installed. 		
B101 02	8/03/10	KS	T/S: 08/02/2010 03:19 PM KSLATTUM		
	8/03/10	AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRII # . 001963133		
	-,, 	111	T/S: 08/02/2010 03:29 PM JBROCK		
B101 03	9/27/10	BS	T/S: 10/12/2010 11:25 AM NTART		
	9/27/10	CA	no footing found at jobsite:42 PM BSUTTON		
B103 01	10/13/10	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001993245		
	10/13/10	AP	1/S: 10/12/2010 11:26 AM NTART		
R325 01	12/01/10	KS	this is a storage building being converted to a SED		
	12/01/10	DA	THREE TRADE ROUGH IN TIME: 17:00 VRU #: 002013340		
	,,		T/S: 11/30/2010 01:44 PM JBROCK		
			PER CUSTOMER INSULATION IS ALREADY UP BUT THERE HAS NEVER BEEN A ROUGH IN		
			T/S: 12/01/2010 02:12 PM KSLATTUM		
			1. Need 2 20 amp circuits for kitchen		
			2. Need 20 amp circuit for washer		
			3. Need 20 amp circuit for bathroom and receptable shall be		
			within 36 inches of sink.		
			4. Window at top of stairs shall be low E and meet egress		
P325 02	5/03/11	7.0	requirements of R310		
N325 U2	5/03/11	BS	THREE TRADE ROUGH IN TIME: 17:00 VRU #: 002074813		
	5/03/11	AP	1/S: 05/02/2011 12:06 PM VBROWN		
			Need smoke detectors up and down. Service drop must be 10' above grade min. Check all at final		
R329 01	10/24/11	BS	THREE TRADE FINAL TIME: 17:00 VRU #: 002151991		
	10/24/11	DA	PLumbing/gas piping ok. Correct electrical problems		
			CONTINUED ONTO NEXT PAGE		

PREPARED 4/16/12, 13:55:21
Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

PAGE 3
DATE 4/17/12

______ SUBDIV: CAPTAINS LANDING ADDRESS . : 37 NATCHEZ TRACE

CONTRACTOR :

OWNER . . : MILLS KENNETH & DORIS

PHONE : PHONE :

PARCEL . . : 05-0613- - -0244- - -

APPL NUMBER: 10-50023725 CP ADD & ALTER RESIDENTIAL

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R329 02	10/28/11	BS	THREE TRADE FINAL TIME: 17:00 VRU #: 002154607
	10/28/11	AP	Trades final only. Will not approve for power until CO is issued
A814 01	10/31/11	FB	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 002155992
	10/31/11	AP	T/S: 10/31/2011 03:08 PM DJOHNSON
			T/S: 10/31/2011 03:15 PM FBURGESS
			37 NATCHEZ TRACE FUQUAY VARINA, NC 27526 LOT 3
R131 01	11/01/11	BS	ONE TRADE FINAL TIME: 17:00 VRU #: 002155927
	11/01/11	CA	T/S: 10/31/2011 01:46 PM DJOHNSON
			T/S: November 01, 2011 10:42 AM BSUTTON
R429 01	1/12/12	BS	FOUR TRADE FINAL TIME: 17:00 VRU #: 002180180
	1/12/12	DA	T/S: 01/10/2012 04:05 PM VBROWN
			HVAC not complete. Must be complete to get final inspection
			ok to cover ductwork on rear of house
R429 02	2/27/12	MR	FOUR TRADE FINAL TIME: 17:00 VRU #: 002197325
	2/27/12	DA	T/S: 02/27/2012 01:41 PM MREARIC
			duct work at back of house still must be closed in , house
			not ready for final
R429 03	4/11/12	BS	FOUR TRADE FINAL TIME: 17:00 VRU #: 002214039
	4/11/12	CA	T/S: 04/10/2012 01:45 PM DJOHNSON
			T/S: April 11, 2012 09:31 AM BSUTTON
R429 04	4/17/12	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002215937