COUNTY OF I Building Inspection Planning S	ns Department
Certificate of Compliance:	Occupancy: $oxed{ imes}$
Certificate issued pursuant to the requirements of North Carolina Gen This certifies at the time of issuance, this structure was in compliance	eral Statute 153A-363 and Harnett County Zoning Ordinances
North Carolina State Building Codes. For the following:	
Use Classification: Residential Name: Barborr Jinny Wayne	Permit Numbers
Name: Borbour Jinmy Wayne	Building:
112(1)	Electrical:
Address: 4864 Baileys Xcals Roll	Insulation:
ZZXIC Bedroom Allitan	Plumbing:
and brecom Alditor	Mechanical: 15
	MFG Home:
Date: 4-8-16 Building Offic	sial: 12-8 / S

PREPARED 4/07/16, 14:06:12 INSPECTION TICKET PAGE 22
Harmet County INSPECTOR: IVR DATE 4/08/16

Harmet County INSPECTOR: IVR DATE 4/08/16

ADDRESS . : 4864 BAILEYS XRDS RD SUBDIV: CONTRACTOR : PHONE :

OWNER . . : BARBOUR JIMMY WAYNE PHONE : (919) 894-2836

PARCEL . .: 07-1611- - -0009- - -

APPL NUMBER: 15-50037266 CP ADD & ALTER RESIDENTIAL
DIRECTIONS: T/S: 10/09/2015 03:25 PM LBENNETT -TAKE HWY 421 TOWARDS DUNN TAKE A LEFT
ON HWY 27 THROUGH CAMPBELL UNIVERSITY
TO COATS TAKE A LEFT ON EBENEZER CHURCH
RD AT BAILEYS CROSSROADS - 3RD BRICK

HOUSE ON THE RIGHT

STRUCTURE: 000 000 22X16 BEDROOM EXPANSION

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 3.00 SEPTIC - EXISTING? : EXISTING

WATER SUPPLY WELL

PERMIT: CPBP 00 CP BUILDING PERMIT		
	REQUESTED IN	NSP DESCRIPTION
TYP/SQ	COMPLETED RES	SULT RESULTS/COMMENTS
B101 01	11/25/15 DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 002745337
	11/25/15 AP	T/S: 11/25/2015 03:42 PM DETAYLOR
B103 01	12/14/15 MR	
	12/14/15 AP	T/S: 12/14/2015 02:13 PM MREARIC
B105 01	1/15/16 DT	R*OPEN FLOOR VRU #: 002765519
	1/15/16 AP	
R125 01	1/22/16 BS	
	1/25/16 DA	
		Job is not ready for rough in, exterior is not ready for
		inspection, not sure what inspection was scheduled for.No
		plans in box
R425 01	3/01/16 KS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002782274
	3/01/16 DA	
	., ,	1. Need test on plumbing tubes and shower liner. 2. Need
		air barrier with R 15 behind the tub.
I129 01	3/03/16 DT	
1125 01	3/03/16 DA	
	3,03,10 Dii	Need test on plumbing. Okay to sheetrock walls excluding
		those that would conceal plumbing drain lines
R425 02	3/03/16 DT	
K425 U2	3/03/16 DA	
	3/03/16 DA	T/S: 03/03/2016 03:27 PM DETAYLOR
		Need test on plumbing. Okay to sheetrock walls excluding
		those that would conceal plumbing drain lines
	2 /1 6 /1 6 DM	
R425 03	3/16/16 DT	
	3/16/16 AP	
R429 01	4/07/16 DT	
	4/07/16 DA	
		Separate back of garage wall from laundry room
R429 02	4/08/16 TI	FOUR TRADE FINAL VRU #: 002800650
	4/8/16	
	•	-

------ COMMENTS AND NOTES -----