

HTE #: 17-5-41215

HARNETT COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH
307 CORNELIUS HARNETT BOULEVARD
LILLINGTON, NC 27546

EXISTING SEPTIC SYSTEM INSPECTION

Name: Mike Langdon

Phone #: 919-422-6946

Address: 150 Lansing Drive Benson, NC 27504

Name of Mobile Home Park or S/D: NA

Name of Owner (if different): Vickie Stephenson

Address of Owner (if different): 2349 Crawford Road Dunn, NC 28334

Property Location (State Road name and #): 1234 Prospect Church Road (SR 2009)

Purpose of Inspection: Bedroom Addition (22'x29') - Adding a bedroom and transitioning another to lounge/study. SFD will remain 3 bedroom.

The aforementioned site has been evaluated by the Harnett County Health Department Environmental Health Section. At the time of inspection, there appeared to be a septic system serving this site. If the system should malfunction, the owner is responsible for any necessary repairs.

THIS INSPECTION IS VOID IF:

1. the intended use of the septic system should change, and/or
2. the system should fail or malfunction, and/or
3. the owner or tenant of the property change, and/or
4. after six months

**BUILDING MUST BE 5' FROM ANY PART OF SEPTIC SYSTEM
DO NOT DRIVE OR PARK ON SEPTIC SYSTEM**

AUTHORIZATION OF EXISTING SYSTEM


Signature of Environmental Health Specialist

05/18/2017
Date